

[Home Page](#) / [Agriculture](#) / [Sprayers](#) / [Sprayer: Self Propelled](#)

Apache AS720 4x4 Self Propelled Sprayer

ITEM# **5407941**
LOCATION **Tchula, Mississippi, United States, 39169**



(92 - photos & videos)

[Print](#)

[Add to Watch List](#)

ITEM DETAILS

METER READING **1,152 Hours**
SERIAL # **9141146**

Hydraulic Driven Pump, 750 gal Fiberglass Tank, Chemical Mix Tank, 380/80R38 Front Tires, 380/90R46 Rear Tires

 [RB Assist](#)
[Cookie Preferences](#)



IronClad Assurance [i](#)



Financing [i](#)

- Inspection Report
- Important Information

INSPECTION REPORT

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.

MODEL DESCRIPTION

DESCRIPTION	DETAILS
Protected by IronClad Assurance®	

GENERAL APPEARANCE

DESCRIPTION	RATING	DETAILS	
Serial Number / VIN		9141146	
Paint			
Sheet Metal (Fiberglass) Condition			
Glass		No visible damage	
Exterior Lights		Operational	
Steps/Ladders			
Hand Rails			













(16)

SAFETY

DESCRIPTION	RATING	DETAILS	
Horn		Operational	
Seat Belts		Operational	RB Assist

Cookie Preferences

CONTROL STATION

DESCRIPTION	RATING	DETAILS	
Mirrors			
Seats/Armrests			
Passenger seat			
Hydraulic Controls			
Steering Control			
Drivetrain Controls			
Oil Pressure		The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights		Operational	
Gauges		Operational	
Hour Meter (pre-inspection)		1151.8 hrs	
Hour Meter		1152.3 hrs, Operational hour meter - No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.	
Air Conditioner		Operational	
Heater		Not operationally checked	
Limited Function Check		The main components are in place and operational as noted.	













(19)

ENGINE

RB Assist





Cookie Preferences

DESCRIPTION	RATING	DETAILS	
A/C Compressor		Operational	
Blow-by (subjective visual observation)		No noticeable vapor or pressure	
Starter		Operational	
Exhaust System			
Radiator			
Oil Leaks		No dripping leaks	
Fuel Leaks		No dripping leaks	
Cooling System Leaks		No dripping leaks	
Engine - Left Side			
Engine - Right Side			
Limited Function Check		The engine started and ran.	



DRIVETRAIN

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

DESCRIPTION	RATING	DETAILS	
Transmission			
PTO		Operational	
PTO Clutch		Electric Clutch	
Drive/Propel Motors			
Rear Drive Axle			
Limited Function Check		The drivetrain was operational.	









HYDRAULICS



RB Assist

[Cookie Preferences](#)

See photos for condition

DESCRIPTION	RATING	DETAILS
Pumps (Hydraulics)		
Valves		
Hydraulic Tank		
Hoses		
Cylinder(s)		
Cylinder Pins and Bushings		

















Limited Function Check

The hydraulic system was operational.



CHASSIS

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

DESCRIPTION	RATING	DETAILS
Booms and Boom Tree		
Boom Shocks		
Tank		
Tank Saddle		
Plumbing		
Pressure Gauge System		
Controller		
Steering Linkage		
Brake Type		Hydraulic 
Brake Control		
Brake Lines/Hoses		
Park Brake		
Limited Function Check - Brakes		The brake system functioned, stopping and holding the machine.
Frame Condition		
Left Front Tire		
Left Rear Tire		
Right Rear Tire		
Right Front Tire		
Tread Depth		LF 8/32", LR 34/32", RR 34/32", RF 2/32" 
Wheel Condition		
Wheel Studs, Nuts, Lugs		



Disputes:

This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not

Cookie Preferences



RB Assist

substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

 **Need help? [Contact Us](#)**

 **North America** ▾ **English** ▾

Company



Support



Our family of sites



Popular categories



Stay connected



Download Our Mobile App



App Store

Google play

Copyright © 1999-2021 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal ServicesSM, TruckPlanet®, GovPlanet®, Kruse EnergySM, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.



RB Assist

Cookie Preferences