



Aspen Field Services

Job #: 27922 /

Serial #:

TTHA1222VK0131058

For more information, visit:

wellsfargo.com/equipseller

TEREX TA400 ART DUMP TR



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/uJ65QyScrMGcWwMNx/full_report_0027922_uJ65QyScrMGcWwMNx.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2019
Make	Terex
Model	TA400
Serial Number	TTHA1222VK0131058
Type	Dump Truck
Inspection Date	2/17/2021
Location of Business	JJ Kane Auctioneers - 95 3rd St NE , Graysville, AL, 35073, USA
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Driver Seat	Good Condition
Passenger Seat	Good Condition
Controls	Standard
Keyless Start	None
Foot Pedals	Good Condition
Hours	17



Aspen Field Services

Job #: 27922 /

Serial #:

TTHA1222VK0131058

For more information, visit:

wellsfargo.com/equipmentseller

TEREX TA400 ART DUMP TR

Inspection Details Cont'd	
Odometer	43 MI 70 KM
Cab A-C	Yes
Cab Heat	Good Condition
Cab A/C Condition	Good Condition
Cab Heat Condition	Good Condition
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Magna: Not Available
Front Right Tire Depth Percentage	Above 50%
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	Above 2"
Front Right Tire Size	29.5R25
Front Left Tire Part Number	Magna: Not Available
Front Left Tire Depth Percentage	Above 50%
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	Above 2"
Front Left Tire Size	29.5R25
Back Right Tire Part Number	Magna: Not Available
Back Right Tire Depth Percentage	Above 50%
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	Above 2"
Back Right Tire Size	29.5R25
Back Left Tire Part Number	Magna: Not Available
Back Left Tire Depth Percentage	Above 50%
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	Above 2"
Back Left Tire Size	29.5R25
Right Middle Tire Part Number	Magna: Not Available
Right Middle Tire Depth Percentage	Above 50%
Right Middle Tire Condition	Good Condition
Right Middle Tire Depth Measurement	Above 2"
Right Middle Tire Size	29.5R25
Left Middle Tire Part Number	Magna: Not Available
Left Middle Tire Depth Percentage	Above 50%
Left Middle Tire Condition	Good Condition
Left Middle Tire Depth Measurement	Above 2"
Left Middle Tire Size	29.5R25
Left Lift Cylinder	Good Condition
Right Lift Cylinder	Good Condition
Lift Cylinder Operations Test	Operational

Inspection Details Cont'd	
Left Articulation Cylinder	Good Condition
Right Articulation Cylinder	Good Condition
Tailgate Lights	Operational
Head Lights	Good Condition
Cab Door	Good Condition
Side Glass Complete	Yes
Muffler	Good Condition
Intake Screen	Good Condition
Engine Door	Good Condition
Engine Compartment	Clean
Engine MFR	Not Visible
Customer Decals Visible on Unit	Yes
Steps	Good Condition
Mismatched Tires	No
Backup Camera	Yes
Comments	The brake lights are non operational.