



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

INSPECTOR: 5750  
 INSPECTION ID  
 117879

CLIENT  
 504 - Wells Fargo MSG  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 05/19/2020 | | FM050420 |

Year, Make:	2015, JOHN DEERE	Full VIN:	1M0220SAHFM050420
Model:	220SA	Engine Make:	
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

**Note and photograph any body damage including scrapes, dents and glass:**  
 GOOD

**Note and photograph any major oil or fluid leaks:**  
 GOOD

**Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.**  
 GOOD

**Note any unusual engine noises or knocks:**  
 GOOD

**List and photograph any tires with uneven wear:**  
 TIRES WORN

**Additional Comments:**  
 NO HOURMETER

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
TIRES WORN	



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
 504 - Wells Fargo MSG  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 05/19/2020 | | FM050420 |

INSPECTOR: 5750  
 INSPECTION ID  
 117879



45 DEGREE BEAUTY SHOT



SERIAL #



ENGINE



MODEL #



LEFT FRONT



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 2



ADDITIONAL 8



ADDITIONAL 15



ADDITIONAL 12



ADDITIONAL 9



ADDITIONAL 10



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
504 - Wells Fargo MSG  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
05/19/2020 | | FM050420 |

INSPECTOR: 5750  
INSPECTION ID  
117879



ADDITIONAL 11



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 16