	BOBCAT EQUI			ore informatio argo.com/equ	on, visit: uipmentseller			G	Truck, Tra	Vehicle Inspection Grou ctor, Trailer, and Equipment s throughout North America info@cvigna.co
Make:	Bobcat		Type:	•	t Track Load	er	Inspector:		GP	
Model: SN:	T76 B4CE16679		Hours: Year:	1817 2021			Inspection Date:		10/3/2024	
SPECIFICA	ATIONS									
ROPS:		Yes	Hours:		1817					
Enclosed	Cab:	Νο	Cab Heat:		No	Cab A/C:	No	Cor	ntrols:	Selectable Joystick Controls
Attachmer	nt on Machine:	74" Bucket								
Additional	Attachments:	N/A								
2-Speed:		No	Engine MFR:		DOOSAN		Tracks			
High Flow Hydraulics - Sticker:		No	Power Bob-T	ach:	No			Key	less Start:	Yes
Backup Camera:		No	Ride Control:		No	Deluxe Instrumenta	tion: Yes			
Hydraulic X-Change: No		No								
Comment	s and Defects:	HYDRAULI	C DRIVE NOIS	Y,						

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit: wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group Truck, Tractor, Trailer, and Equipment Inspections throughout North America 203-628-4325 info@cvigna.com

Tire Fault Legend							
C - Cut	D - Dry	F - Flat	M -	Mismatched Tread / Casings			
WD - Wheel Damage							
TRACKS							
Make:	NA		Make:	NA			
Part #:	NA		Part #:	NA			
Measure:	32 / 32		Measure:	32 / 32			
Condition:	GOOD		Condition:	GOOD			
Tread Remaining:	Over 50%		Tread Remaining:	Over 50%			
Fault:			Fault:				

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit: wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group Truck, Tractor, Trailer, and Equipment Inspections throughout North America 203-628-4325 info@cvigna.com

CONDITION REPORT

	Check	Comments / Deficiencies
✓	Visual Inspection	CLEAN
х	Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN - HYDRAULIC SYSTEM NOISY - DIAGNOSE
\checkmark	Lift Cylinders	NO LEAKS
\checkmark	Tilt Cylinders	NO LEAKS
\checkmark	Boom Arms Operations	WORKING
\checkmark	Seat	GOOD CONDITION
\checkmark	Tailgate Lights	GOOD CONDITION
Х	Working Lights	BROKEN - RIGHT SIDE
N/A	Front Door	
\checkmark	Rear and Top Window	NO DAMAGES
✓	Side Glass Complete	NO DAMAGES
✓	Boom Arms Damages	NO DAMAGES
✓	Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓	Mufflers	GOOD CONDITION
✓	ROPS Condition	GOOD CONDITION
Х	Power Bob-Tach Condition	MISSING
N/A	Cab A-C Condition	
N/A	Cab Heat Condition	
✓	Intake Screen	GOOD CONDITION
✓	Eng. Compartment	
N/A	Hydraulic X-Change Condition	
✓	Customer Decals Visible on Unit	NO
Х	Error Codes	YES - SERVICE CODES PRESENT - DIAGNOSE
Х	Condition Report	LEFT AND RIGHT SIDE DRIVE SPROCKETS WORN





Front Left

Front Right





Seating / Interior

Rear









PHOTOS







































