


# 2017 HAMM HD+110IVV

UNIT: H2420127

[Download Reconditioning Printout](#)








## UNIT SPECS

**Customer** Wells Fargo (IMS)

## LOCATION

**Wells Fargo (IMS)**   
Please call Pickup Support for location information  
Morris, IL 60450

### GENERAL APPEARANCE

<b>UID</b>	H2420127	<b>CE Mark</b>	CE Marked
<b>Paint</b>	No visible damage	<b>Sheet Metal (Fiberglass) Condition</b>	No visible damage or missing components
<b>Cab/Canopy Overhead Structural Framework</b>	No visible damage	<b>Steps/Ladders</b>	No visible damage or missing components.
<b>Exterior Lights</b>	2 Inoperable / damaged / missing		

### MODEL DESCRIPTION

**Model** HD+110iVV

### SAFETY

<b>Travel Alarm</b>	Operational	<b>Horn</b>	Operational
<b>Seat Belts</b>	Operational	<b>Safety Lock Out/Stop</b>	Operational

### CONTROL STATION

<b>Cab Configuration</b>	Swivel Operator Controls	<b>Seats/Armrests</b>	No visible damage or missing components
<b>Steering Control Rating</b>	Good	<b>Hydraulic Controls Rating</b>	Good
<b>Drivetrain Controls Rating</b>	Good	<b>Dash Console Rating</b>	Good

**Oil Pressure**  
The fault indicator shuts off after the engine oil pressure rises.

**Warning Lights** Operational

**Gauges** Operational

**Hour Meter/Odometer (Start)** 2381 hrs **Hour Meter/Odometer** 2381 hrs, Operational hour meter

**Limited Function Check (Control Station)**  
The main components are in place and operational as noted.

## ENGINE

**Emission Certification Label** 2017 US EPA Label

**Engine Make**  
Deutz Diesel Engine, Requires Diesel Exhaust Fluid

**Engine Model** TCD3.6 L4

**Engine Horsepower** 114 hp

**Engine Displacement** 3.6 L

**Blow by @ idle (subjective visual observation)**  
No noticeable vapor or pressure

**Starter** Operational

**Exhaust System**  
No visible damage or missing components

**Radiator Rating** Good

**Oil Leaks?** No dripping leaks

**Limited Function Check (Engine)**  
The engine started and ran.

## DRIVETRAIN

**Transmission Type** Hydrostatic transmission

**Left Front Drive Motor Rating** Good

**Left Rear Drive Motor** Good

**Limited Function Check (Compaction)**  
The drivetrain was operational without a load.

## HYDRAULICS

**Pumps (Hydraulics) Rating** Good

**Valves Rating** Good

**Hydraulic Tank Rating** Good

**Hoses/Lines Compactor Rating** Good

**Hydraulic Vibrator Motors Rating** Good

**Steering Cylinders Rating** Good

**Limited Function Check (Hydraulics)**  
The hydraulic system was operational.

## CHASSIS

**Compaction Width** 66 in Drums, Water System

**Drum Condition Rating** Good

<b>Rubber Drum Isolators Rating</b>	Good	<b>Drum Scraper Rating</b>	Good
<b>Water System Rating</b>	Good	<b>Frame Condition Rating</b>	Good
<b>Articulating Center Pins Rating</b>	Good	<b>Park Brake Rating</b>	Good
<b>Limited Function Check (Roller)</b>			
The main chassis components were operational.			

## RECONDITIONING

<b>Exterior Lights - 2 Inop/Damaged/Missing</b>	<b>\$400</b>
<b>Total</b>	<b>\$400</b>