



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/rqsYjZgzSFMx9AFyy/full_report_0026117_rqsYjZgzSFMx9AFyy.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Vogele
Model	5100-2
Serial Number	13820132
Type	Paver
Inspection Date	12/04/2020
Location of Business	JJ KANE - 3020 Commercial Rd , Fort Wayne, IN, 46809, USA
Attachment(s)/ Accessory(s)	None
Engine MFR	Vogele
Controls	Standard
Hours	6138
Keyless Start	No
Visual Inspection	Clean
Operational Test	Passed
Left Track Condition	Gauges



Aspen Field Services

Job #: 26117 /

Serial #: 13820132

2017 VOGELE 5100-2

For more information, visit:

wellsfargo.com/equipmentseller

Inspection Details Cont'd	
Left Track Part Number	Not Available
Left Track Tread Depth Percentage	Less than 50%
Left Track Tread Depth Measurement	25/32"
Right Track Condition	Good
Right Track Part Number	Not Available
Right Track Tread Depth Percentage	Less than 50%
Right Track Tread Depth Measurement	24/32"
Mismatched Tracks	No
Cylinders	Good
Material Hoppers Operations	Not Available
Seat	Tear
Tailgate Lights	Not Available
Working Lights	Not Available
Material Hoppers Damages	None
Engine Door	Opens and Closes/Stays Closed
Mufflers	Good Condition
Intake Screen	Good Condition
Engine Compartment	Dirty
Customer Decals Visible on Unit	No
Engine Serial Number	22112420
Comments	The material hopper pads need to be replaced. The tar needs to be cleaned out of the hopper and belt.

Inspection Details Cont'd