



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSPECTOR: 5761
INSPECTION ID
134399

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

Year	2016	Make	PREVOST
Model	H3-45	VIN	2PCH33497GC713310

SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	BLUE

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13
Eng Serial:	0131136386
Eng HP:	500
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	149
Overall Width:	102

Engine Options B	
Odometer:	380104
Hub odometer:	
ECU HP:	
ECU Miles:	
Eng Hours:	N/A

Engine Options C	
Eng Brake:	NONE
Fuel:	DIESEL
FT1 Capac (Gal):	222

Exterior Options A	
Air Horns:	SINGLE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	316.
Rear Ratio:	
F Axle (lbs):	19000
R Axle (lbs):	22500
GVWR (lbs):	55000
Suspension:	AIR RIDE
Tag Axle Capacity:	14000
Rear Axle Model:	
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	B500
Trans Speed:	6

Miscellaneous	
Seating Capacity:	43
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	6
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	No
Global Positioning System:	No
In Motion Satellite TV System:	No
Road Viewing Monitor System:	No
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	Yes
Was Unit towed in ?:	No
Did Unit start and run ?:	No
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NO POWER, WOULD NOT JUMP
Any extra options or features not listed on front page and any additional comments:	



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSPECTOR: 5761
INSPECTION ID
134399

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes





Drive Axle Brakes:	(1)
	(2)
	(3)
	(4)
	(5)

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
RIGHT		13 / 32nd HIGHWAY / V	13 / 32nd HIGHWAY / V
	15 / 32nd HIGHWAY / V		
FRONT		10 / 32nd HIGHWAY / V	/ 32nd HIGHWAY / V
		11 / 32nd HIGHWAY / V	/ 32nd HIGHWAY / V
LEFT	13 / 32nd HIGHWAY / V		
		16 / 32nd HIGHWAY / V	16 / 32nd HIGHWAY / V

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSPECTOR: 5761
INSPECTION ID
134399

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

CONDITION REPORT

Engine Compartment Area			COMMENTS	
Operational Test			COMMENTS	
X	Batteries - Capable of Starting Engine	WILL NOT JUMP		
In Cab Inspection			COMMENTS	
X	Windshield, Door & Any Other Glass	MINOR CHIPS		
Outside Inspection			COMMENTS	
Under Vehicle Inspection			COMMENTS	
Tires/Wheels/Brakes			COMMENTS	
Additional Services		Requested	Status	Comments



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSPECTOR: 5761
INSPECTION ID
134399

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Batteries - Capable of Starting Engine	X WILL NOT JUMP
Windshield, Door & Any Other Glass	X MINOR CHIPS
UNABLE TO SCAN/CONNECT	ENGINE LIGHTING ON / SHUTDOWN
UNIT REQUIRED A JUMP	BUT WAS NOT SUCCESSFUL

COMMENTS:

UNIT OBSERVED IN GOOD OVERALL USED CONDITION. CALLED AHEAD AND YARD ADVISED UNIT WAS DRIVEN IN AND STARTS. UPON ARRIVAL UNIT WOULD START ACCESSORIES OPTIONS AND DASH BUT WOULD NOT TURN OVER MOTOR. HAD YARD ATTACH CHARGER AND JUMPER AND WE WAITED FOR A WHILE AND STILL COULD NOT GET TO TURN OVER AND START. COMPLETED INSPECTION WITHOUT. PLEASE SEE DASH CODES THAT CAME UP.



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

INSPECTOR: 5761
INSPECTION ID
134399



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO
BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

INSPECTOR: 5761
INSPECTION ID
134399



INSIDE OF BUS, BACK TO FRONT



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 18



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

INSPECTOR: 5761
INSPECTION ID
134399



ADDITIONAL 19



ADDITIONAL 20




ADDITIONAL 21



ADDITIONAL 22



ADDITIONAL 23



ADDITIONAL 24



ADDITIONAL 25



ADDITIONAL 26



ADDITIONAL 27




ADDITIONAL 28



ADDITIONAL 29



ADDITIONAL 30



ADDITIONAL 31



ADDITIONAL 32



ADDITIONAL 33



ADDITIONAL 34



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
12/16/2020	115	GC713310	

INSPECTOR: 5761
INSPECTION ID
134399



ADDITIONAL 35



ADDITIONAL 36



ADDITIONAL 37