



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | 25155 |

INSPECTOR: 5750
 INSPECTION ID
 117864

Year, Make:	2015, BUFFALO	Full VIN:	25155
Model:	CYCLONE KB4	Engine Make:	
Engine Model:		Clean air idle:	
Classification:			

Note and photograph any body damage including scrapes, dents and glass:
 GOOD

Note and photograph any major oil or fluid leaks:
 GOOD

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.
 GOOD

Note any unusual engine noises or knocks:
 GOOD

List and photograph any tires with uneven wear:
 TIRES WORN

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
TIRES UNDER 50\$	
HOUR METER 2563	



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | 25155

INSPECTOR: 5750
 INSPECTION ID
 117864



RIGHT REAR



SERIAL #



LEFT REAR



REAR



RIGHT FRONT



FRONT



FRONT LEFT



HOUR METER



TIRE



TIRE



ENGINE



ADDITIONAL 5