

2017 HAMM HD+110IVV

UNIT: H2420104

 Download Reconditioning Printout








UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS) 
Please call Pickup Support for location information
Morris, IL 60450

GENERAL APPEARANCE

UID	H2420104	CE Mark	CE Marked
Paint	No visible damage	Sheet Metal (Fiberglass) Condition	No visible damage or missing components
Cab/Canopy Overhead Structural Framework	No visible damage	Steps/Ladders	No visible damage or missing components.
Hand Rails	No visible damage or missing components	Exterior Lights	2 Inoperable / damaged / missing

MODEL DESCRIPTION

Model HD+110iVV

SAFETY

Travel Alarm	Operational	Horn	Operational
Seat Belts	Operational	Safety Lock Out/Stop	Operational

CONTROL STATION

Cab Configuration	Swivel Operator Controls	Seats/Armrests	No visible damage or missing components
Steering Control Rating	Good	Hydraulic Controls Rating	Good
Drivetrain Controls Rating	Good	Dash Console Rating	Good
Oil Pressure The fault indicator shuts off after the engine oil pressure rises.		Warning Lights	Operational
		Gauges	Operational
Hour Meter/Odometer (Start)	2275 hrs	Hour Meter/Odometer	2275 hrs
Limited Function Check (Control Station) The main components are in place and operational as noted.			

ENGINE

Emission Certification Label	2017 US EPA Label	Engine Make	Deutz
Engine Model	TCD3.6 L4	Engine Horsepower	114 hp
Engine Displacement 3.6 L Diesel Engine, Requires Diesel Exhaust Fluid		Blow by @ idle (subjective visual observation) No noticeable vapor or pressure	
Starter	Operational	Exhaust System No visible damage or missing components	
Radiator Rating	Good	Oil Leaks?	No dripping leaks
Limited Function Check (Engine) The engine started and ran.			

DRIVETRAIN

Transmission Type	Hydrostatic transmission	Left Front Drive Motor Rating	Good
Left Rear Drive Motor	Good	Limited Function Check (Compaction) The drivetrain was operational without a load.	

HYDRAULICS

Pumps (Hydraulics) Rating	Good	Valves Rating	Good
Hydraulic Tank Rating	Good	Hoses/Lines Compactor Rating	Good
Hydraulic Vibrator Motors Rating	Good	Steering Cylinders Rating	Good
Limited Function Check (Hydraulics) The hydraulic system was operational.			

CHASSIS

Compaction Width	66 in Drums, Water System	Drum Condition Rating	Good
Rubber Drum Isolators Rating	Good	Drum Scraper Rating	Good
Water System Rating	Good	Frame Condition Rating	Good
Articulating Center Pins Rating	Good	Park Brake Rating	Good
Limited Function Check (Roller) The main chassis components were operational.			

RECONDITIONING

Exterior Lights - 2 Inop/Damaged/Missing	\$400
Total	\$400