



CONDITION REPORT

Make: Shuttlewagon
Model: NVX9060
S/N: 906019030
Hours: 1277
Date of Inspection: 8/15/2023

Overview:

The unit is in good condition.

Items that need Addressed:

Replace tires.
Inspect to find cause of hydraulic leak under cab.

Visual Inspection

Oil Leaks	Small hydraulic leak under cab.
Air Leaks	Good
Tires	Poor – needs replaced.
Windows	Good
Body Damage	Good
Lights	Good
Engine Mount Bolts	Good
Transmission Mount Bolts	Good
Road Axle Mount Bolts	Good

Operational Inspections

Engine Performance	Good
--------------------	------



Service Brakes	Good
Park Brake	Good
Train Brakes	Good
Directional Lever	Good
Steering Operation/Linkage	Good
Hydraulic Control	Good
Instrumental Gauges	Good
Safety Equipment and Lights	Good
Sander Operation	Good
Remote System	N/A – Unit does not have remote
Cameras	Good
Block Heater	N/A
Cab Heater	Good
Wipers	Good
Door Handles	Good
Accelerator Pedal (Front/Rear Pedal or Joystick)	Good

Service Check Points

Radiator Level	Good
Condition of Radiator and Hoses	Good
Engine Oil Level	Good
Engine Oil Filter	Good
Air Filter	Poor – Needs replaced
Belts	Good
Fuel Filter	Good
Battery Hold Down and Connections	Good
Rail Wheel Bolts	Good
Differential Bolts	Good
Front Axle Fluid Levels	Good
Planetary Fluid Levels	Good
Road Wheel Bolts	Good
Hydraulic Oil Level	Good
Compressor Oil Level	Good
U-Joints	Good
Parking Brake Operation	Good
Parking Brake Pads	Good

Def Fluid Level	Good
Rail Wheel Condition	Good
Road Tires	Poor – Needs placed
Batteries	Good

































































































