



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499

Year	2016	Make	VOLVO
Model	9700	VIN	3CET2V224G5173407

### SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	BLUE

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13J435P
Eng Serial:	89030289
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	11'
Overall Width:	8'

Engine Options B	
Odometer:	179759
Hub odometer:	NA
ECU HP:	500
ECU Miles:	179768
Eng Hours:	NA

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	
Any extra options or features not listed on front page and any additional comments:	
NA	

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	210

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	BLUE

Axle / Susp Options	
WheelBase (In):	315
Rear Ratio:	2.64
F Axle (lbs):	16,500
R Axle (lbs):	10,800
GVWR (lbs):	49,000
Suspension:	AIR RIDE
Tag Axle Capacity:	22,100
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	No
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	VOLVO
Trans Model:	I-SHIFT
Trans Speed:	12



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499

### Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

### Brakes









Steer Axle Brakes:	50%	50%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

### Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

### Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		9 / 32nd LUG / R1	6 / 32nd LUG / R1
RIGHT	5 / 32nd HIGHWAY / V 	 	 
FRONT		10 / 32nd LUG / R1	/ 32nd /
LEFT	 15 / 32nd HIGHWAY / V	9 / 32nd LUG / R1 	/ 32nd / 
		8 / 32nd LUG / R1	5 / 32nd LUG / R1

### Brake Legend

**BD = DRUM HAS MORE THAN 1/16 INCH LIP**  
**CL = CRACKED LINING**  
**LS = LEAKING SEAL(S)**

### Tire Legend

**C = CUT D = DRY ROT F = FLAT**  
**M = MISMATCHED TIRES/CASING**  
**MA = MISMATCHED AXLES (FRONT vs. REAR)**  
**V = VIRGIN W = IRREGULAR WEAR**  
**R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES**

### Tread Legend

**H = HIGHWAY L = LUG**



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499

CONDITION REPORT

	Engine Compartment Area	COMMENTS
	Operational Test	COMMENTS
	In Cab Inspection	COMMENTS
	Outside Inspection	COMMENTS
X	Lights and Reflectors	RIGHT TAIL LAMP DAMAGED
	Under Vehicle Inspection	COMMENTS
	Tires/Wheels/Brakes	COMMENTS
X	Tires/Wheels	3 BAD TIRES

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## **BUS**

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499

### RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Lights and Reflectors	X   RIGHT TAIL LAMP DAMAGED
Tires/Wheels	X   3 BAD TIRES
FRONT BUMPER	DAMAGED

#### COMMENTS:

THE BUS WAS INSPECTED AT PREVOST. THE BATTERIES WERE BEING REPLACED AT THE TIME OF MY INSPECTION. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE FRONT BUMPER, RIGHT TAIL LAMP AND THE RIGHT SIDE CARGO DOOR HANDLES. THERE ALSO THREE BAD TIRES.



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT  
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO  
BACK



DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

126499




FLOOR OF BUS, FRONT TO  
BACK



INSIDE OF BUS, BACK TO  
FRONT



FLOOR OF BUS, BACK TO  
FRONT



INSIDE RESTROOM #1



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT  
RIGHT SIDE



ENGINE COMPARTMENT LEFT  
SIDE



INSIDE STORAGE  
COMPARTMENTS



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4





**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## **BUS**

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/23/2020

FLEET NAME

UNIT NUMBER

5613

VIN (LAST 8)

G5173407

PO NUMBER

INSPECTOR: 5932

INSPECTION ID


126499



ADDITIONAL 5




ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8




ADDITIONAL 9



ADDITIONAL 10




ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13



ADDITIONAL 14