

2017 HAMM HD+110IVV

UNIT: H2420071

[Download Reconditioning Printout](#)






UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS) 
Please call Pickup Support for location information
Morris, IL 60450

GENERAL APPEARANCE

UID	H2420071	CE Mark	CE Marked
Paint	No visible damage	Sheet Metal (Fiberglass) Condition	No visible damage or missing components
Cab/Canopy Overhead Structural Framework	No visible damage	Steps/Ladders	No visible damage or missing components.
Hand Rails	No visible damage or missing components	Exterior Lights	2 Inoperable / damaged / missing

MODEL DESCRIPTION

Model HD+110iVV

SAFETY

Travel Alarm	Operational	Horn	Operational
Seat Belts	Operational	Safety Lock Out/Stop	Operational

CONTROL STATION

Cab Configuration Swivel Operator Controls

Seats/Armrests

No visible damage or missing components

Steering Control Rating Good

Hydraulic Controls Rating Good

Drivetrain Controls Rating Good

Dash Console Rating Good

Oil Pressure

The fault indicator shuts off after the engine oil pressure rises.

Warning Lights Operational

Gauges Operational

Hour Meter/Odometer (Start) 2153 hrs

Hour Meter/Odometer 2153 hrs, Operational hour meter

Limited Function Check (Control Station)

The main components are in place and operational as noted.

ENGINE

Emission Certification Label 2016 US EPA Label

Engine Make

Deutz Diesel Engine, Requires Diesel Exhaust Fluid

Engine Model TCD3.6 L4

Engine Horsepower 114 hp

Engine Displacement 3.6 L

Blow by @ idle (subjective visual observation) Good

Starter Operational

Exhaust System

No visible damage or missing components

Radiator Rating Good

Oil Leaks? No dripping leaks

Limited Function Check (Engine)

The engine started and ran.

DRIVETRAIN

Transmission Type Hydrostatic transmission

Left Front Drive Motor Rating Good

Left Rear Drive Motor Good

Limited Function Check (Compaction)

The drivetrain was operational without a load.

HYDRAULICS

Pumps (Hydraulics) Rating Good

Valves Rating Good

Hydraulic Tank Rating Good

Hoses/Lines Compactor Rating Good

Hydraulic Vibrator Motors Rating Good

Steering Cylinders Rating Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Compaction Width	66 in Drums, Water System	Drum Condition Rating	Good
Rubber Drum Isolators Rating	Good	Drum Scraper Rating	Good
Water System Rating	Good	Frame Condition Rating	Good
Articulating Center Pins Rating	Good	Park Brake Rating	Good
Limited Function Check (Roller) The main chassis components were operational.			

RECONDITIONING

Exterior Lights - 2 Inop/Damaged/Missing	\$400
Total	\$400