



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/aadwouvnfgs9e4nyZ/report_0024407_aadwouvnfgs9e4nyZ.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Master Lease Number	001-0436024-105
Year	2017
Make	Hamm
Model	HD120i VV HF
Serial Number	H2430054
Type	Roller
Inspection Date	9/16/2020
Location of Business	JJ Kane Auctioneers - 95 3rd St NE , Graysville, AL, 35073, USA
Attachment(s)	None
Enclosed Cab	No
Engine MFR	Deutz
Controls	Standard
Hours	2451
Cab A-C	No
Cab Heat	No



Aspen Field Services

Job #: 24407 /

Serial #: H2430054

2017 HD120I VV HF

For more information, visit:

wellsfargo.com/equipmentseller

Inspection Details Cont'd	
Backup Camera	No
Deluxe Instrumentation	No
Keyless Start	No
Visual Inspection	Clean
Operations Test	Operational
Front Roller Condition	Good
Front Roller Thickness	3/4"
Front Roller Diameter	54"
Front Roller Width	78"
Rear Roller Condition	Good
Rear Roller Thickness	3/4"
Rear Roller Diameter	54"
Rear Roller Width	78"
Front and Rear Roller Depth Percentage	Above 50%
Seat	Good Condition
Tailgate Lights	Operational
Working Lights	Non Operational
ROPS Condition	Good Condition
Engine Door	Good Condition
Intake Screen	Good Condition
Articulation Cylinders	Good Condition
Interior Condition	Good Condition
Engine Compartment	Clean
Customer Decals Visible on Unit	None
Comments	The front working lights are non operational.

Inspection Details Cont'd