

# 2022 JOHN DEERE 9900I

UNIT: 1Z09900YVMU622099

[Download Reconditioning Printout](#)



## UNIT SPECS

Customer Wells Fargo (IMS)

## LOCATION

Wells Fargo (IMS)   
Please call Pickup Support for location information  
Hanford, CA 93230

### CHASSIS

Is There A Factory Installed ROPS?  
Yes

Steering Linkage  
Rating:  
Good

Steering Wheel Play

Rating:

Good

Brake Type

Hydraulic

Master Cylinder/Brake Control

Rating:

Good

Brake Lines/Hoses

Rating:

Good

Park Brake

Held against power

Rating:

Good

Limited Function Check - Brakes

The brake system functioned, stopping and holding the machine.

Wheel Condition

Rating:

Good

Wheel Studs

Rating:

Good

## CONTROL STATION

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Gauges

Operational

Hour Meter (Pre-inspection)

2163 hrs

Hour Meter

2163 hrs

Indication Of Additional Hours

The following hour meter reading written on the filters is greater than that on the meter: 2432

Air Conditioner  
Operational

Heater  
Operational

Limited Function Check (Control Station)  
The main components are in place and operational as noted.



Precision Farming  
John Deere Display, No

## DRIVETRAIN

Final Drives  
Rating:  
Good

Limited Function Check (Drivetrain)  
The drivetrain was operational.

## ENGINE

A/C Compressor  
Operational

Starter  
Operational

Radiator  
Rating:  
Good

Oil Leaks  
No dripping leaks

Fuel Leaks  
No dripping leaks

Cooling System Leaks  
No dripping leaks

Limited Function Check (Engine)  
The engine started and ran.



Engine  
No US EPA Label Present Requires Diesel Exhaust Fluid

## GENERAL APPEARANCE

Year  
2022

Make  
John Deere

Model  
9900i

Serial Number / VIN  
1Z09900YVMU622099

Seller Reference Number  
Seller Reference or Fleet Number:7527F118

Hour Meter /Odometer Usage Reading (Start)  
2163 mi

Hour Meter / Odometer  
2163 hrs

Indication Of Additional Hours  
The following hour meter reading written on the filters is greater than that on the meter: 2432

Condition  
Fair

Cab/Canopy Overhead Structural Framework  
No visible damage

## HYDRAULICS

Pumps (Hydraulics)  
Rating:  
Good

Valves  
Rating:  
Good

Hydraulic Tank  
Rating:  
Good

Cylinder(s)  
Rating:  
Good

Cylinder Pins And Bushings  
Rating:  
Good

Limited Function Check (Hydraulics)  
The hydraulic system was operational.

## SAFETY

Seat Belts  
Operational

Current Safety Manual  
No

Current Operator/Maintenance Manual

No

**RECONDITIONING**