



Aspen Field Services

Job #: 26229 /

Serial #:

4UZA EJDU6HCJB1310

For more information, visit:

wellsfargo.com/equipseller

2016 FREIGHTLINER/ARBOC TROLLEY



Video:



PHOTOS: Click the link below to view all high resolution images
https://app.aspenfieldservices.com/api/attachments/get/caqQQiarH3NLdAygE/full_report_0026229_caqQQiarH3NLdAygE.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2016
Make	Freightliner
Model	ARBOC
VIN	4UZA EJDU6HCJB1310
Type	Trolley Bus
Inspection Date	12/9/2020
Location of Business	Polynesian Adventure Tours - 4031 Halau St, Bay #4, Lihue, HI, 96766, USA
Enclosed Cab	Yes
Controls	Standard
Odometer	15175
Cab A-C	Yes
Cab A-C Condition	Good Condition
Cab Heat Condition	Yes
Keyless Start	No
Visual Inspection	Clean



Aspen Field Services

Job #: 26229 /

Serial #:

4UZA EJDU6HCJB1310

For more information, visit:

wellsfargo.com/equipmentseller

2016 FREIGHTLINER/ARBOC TROLLEY

Inspection Details Cont'd	
Operational Test	Operational
Front Right Tire Part Number	Michelin: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	16/32"
Front Right Tire Size	245/70 R19.15
Front Left Tire Part Number	Michelin: Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	15/32"
Front Left Tire Size	245/70 R19.15
Back Right Tire Part Number	Michelin: Not Available
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	15/32"
Back Right Tire Size	245/70 R19.15
Back Left Tire Part Number	Michelin: Not Available
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	17/32"
Back Left Tire Size	245/70 R19.15
Front Lights	Non Operational.
Tailgate Lights	Good Condition
Interior Lights	Good Condition
Driver Seat Condition	Good Condition
Passenger Seat Conditions	Good Condition
Cab Door	Good Condition
Cab Passenger Door	Good Condition
Side Glass Complete	Yes
Side Glass Condition	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Compartment	Clean
Engine MFR	Cummins
Battery Compartment	Dirty
Customer Decals Visible on Unit	Yes
Mismatched Tires	No
Transmission	Allison B220 Automatic
Cab A-C Condition	Good Condition
Cab Heat Condition	Good Condition

Inspection Details Cont'd



Aspen Field Services

Job #: 26229 /

Serial #:

4UZA EJDU6HCJB1310

For more information, visit:
wellsfargo.com/equipmentseller

2016 FREIGHTLINER/ARBOC TROLLEY

Comments	The middle light on the front of the bus has bulbs that have burnt out. A back window panel has been replaced
----------	---