



# Aspen Field Services

Job #: 27941 /

Serial #: 11J1-5016

For more information, visit:

[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)

## KAWASAKI 115Z7 WHEEL LOADER



### Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/Cuy6AQ5AxfnmjGjX/full\\_report\\_0027941\\_Cuy6AQ5AxfnmjGjX.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/Cuy6AQ5AxfnmjGjX/full_report_0027941_Cuy6AQ5AxfnmjGjX.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	Not Available
Make	Kawasaki
Model	115Z7
Serial Number	11J1-5016
Type	Wheel Loader
Location of Inspection	JJ Kane Auctioneers - 15 Pine Street, Deposit, NY, 13754, USA
Hours	5335
Active Warnings	None
Operational Test	Operational
Enclosed Cab	Yes
Controls	Standard
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition



# Aspen Field Services

Job #: 27941 /

Serial #: 11J1-5016

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

KAWASAKI 115Z7 WHEEL LOADER

Inspection Details Cont'd	
Keyless Start	No
Seat	Good Condition
Pedals/Hand Controls	Good Condition
Top Glass	NA
Visual Inspection	Clean
Attachment	Bucket
Attachment Serial Plate	8397101
Quick Coupler	No
Quick Coupler Condition	NA
Left Tilt Cylinder	Good Condition
Right Tilt Cylinder	Good Condition
Lift Cylinders	Good Condition
Left Articulation Cylinder	Good Condition
Right Articulation Cylinder	Good Condition
Boom Arm Left	Good Condition
Boom Arm Right	Good Condition
Front ROPS	Good Condition
Left ROPS	Good Condition
Cab Door	Good Condition
Right ROPS	Good Condition
Rear Glass	Good Condition
Engine Door	Good Condition
Engine Compartment	Dirty
Engine MFR	Not Visible
Intake Screen	Good Condition
Muffler	Good Condition
Backup Camera	Yes
Front Left Tire Brand	Michelin: Not Available
Front Left Tire Condition	Cut
Front Left Tire Size	35/65R33
Front Left Tire Tread Depth Measurement	3"
Front Left Tire Tread Depth Percentage	Above 50%
Back Left Tire Brand	Michelin: Not Available
Back Left Tire Condition	Cut
Back Left Tire Size	35/65R33
Back Left Tire Tread Depth Measurement	3 1/2"
Back Left Tire Tread Depth Percentage	Above 50%
Front Right Tire Brand	Michelin: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Size	35/65R33

Inspection Details Cont'd	
Front Right Tire Tread Depth Measurement	3"
Front Right Tire Tread Depth Percentage	Above 50%
Back Right Tire Brand	Michelin: Not Available
Back Right Tire Condition	Cut
Back Right Tire Size	Not Visible
Back Right Tire Tread Depth Measurement	2 3/4"
Back Right Tire Tread Depth Percentage	Above 50%
Working Lights	Non Operational
Tailgate Lights	Non Operational
Boom Arm Operations	Operational
Date of Inspection	2/16/2021
Comments	The working lights on the cab and both tailgate lights are non operational. The right rear fender is bent. The steps appear to be a little bent as well.