



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	VIN (LAST 8)	PO NUMBER
03/16/2021		J5188041	

INSPECTOR: 5932

INSPECTION ID

138048

Year	2018	Make	VOLVO
Model	9700	VIN	3CET2V921J5188041

SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	BLACK

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13
Eng Serial:	NA
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	12'
Overall Width:	8'

Engine Options B	
Odometer:	121729
Hub odometer:	NA
ECU HP:	500
ECU Miles:	121735
Eng Hours:	NA

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additional comments:	
NA	

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	211

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	315
Rear Ratio:	2.64
F Axle (lbs):	16,500
R Axle (lbs):	10,800
GVWR (lbs):	49,400
Suspension:	AIR RIDE
Tag Axle Capacity:	22,100
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	EATON/FULLER
Trans Model:	3000/4000 5TH GEN
Trans Speed:	12



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

J5188041

INSPECTOR: 5932

INSPECTION ID

138048

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes

Steer Axle Brakes:	50%	50%	(1)
Drive Axle Brakes:	50%	50%	(2)
	50%	50%	(3)
			(4)
			(5)
			(6)

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		14 / 32nd LUG / R1	16 / 32nd LUG / R1
RIGHT	15 / 32nd HIGHWAY / V 	 	 
FRONT		8 / 32nd LUG / R1	/ 32nd /
LEFT	 13 / 32nd HIGHWAY / V	 	 
		10 / 32nd LUG / R1	10 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

J5188041

INSPECTOR: 5932

INSPECTION ID

138048

CONDITION REPORT

	Engine Compartment Area	COMMENTS
	Operational Test	COMMENTS
	In Cab Inspection	COMMENTS
	Outside Inspection	COMMENTS
X	Paint Condition & Physical Damage	BODY DAMAGE
	Under Vehicle Inspection	COMMENTS
	Tires/Wheels/Brakes	COMMENTS
X	Tires/Wheels	2 BAD TIRES

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

J5188041

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

138048

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Paint Condition & Physical Damage	X BODY DAMAGE
Tires/Wheels	X 2 BAD TIRES
FRONT BUMPER	DAMAGED
FRONT PANEL	REFINISH
RIGHT & LEFT SIDE FRONT CORNER PANEL	DAMAGED
RIGHT SIDE PANEL	WET SAND & POLISH
RIGHT SIDE # 2 CARGO DOOR	DAMAGED
RIGHT SIDE # 3 CARGO DOOR	DAMAGED
RIGHT REAR WHEELHOUSE	DAMAGED
RIGHT SIDE CENTER WHEELHOUSE	DAMAGED
RIGHT SIDE ENGINE DOOR	DAMAGED
RIGHT SIDE UPPER VENT	DAMAGED
LEFT SIDE # 3 CARGO DOOR	DAMAGED
LEFT SIDE FRONT WHEELHOUSE	DAMAGED
LEFT SIDE REAR WHEELHOUSE	DAMAGED

COMMENTS:

THE COACH WAS INSPECTED AT THE CUSTOMER'S YARD. THE COACH WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE FRONT BUMPER, FRONT PANEL, RIGHT AND LEFT SIDE FRONT CORNER PANELS, RIGHT AND LEFT SIDE CARGO DOORS, ENGINE SIDE DOOR AND TWO TIRES. THERE WERE TWENTY TWO OUTLETS WITH USB PORTS AND TWO CUP HOLDERS.



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

J5188041

INSPECTOR: 5932

INSPECTION ID

138048



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO
BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

J5188041

INSPECTOR: 5932

INSPECTION ID

138048



FLOOR OF BUS, FRONT TO
BACK



INSIDE OF BUS, BACK TO
FRONT



FLOOR OF BUS, BACK TO
FRONT



INSIDE RESTROOM #1



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



J PRO SCREEN



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/16/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

J5188041

INSPECTOR: 5932

INSPECTION ID

138048



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13



ADDITIONAL 14