

Aspen Field Services

Job #: 30626 / Serial #: 08130123

For more information, visit: wellsfargo.com/equipmentseller









Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/
get/5xSAjrFrkZN6S5LeQ/full_report_0030626_5xSAjrFrkZN6S5LeQ.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Wirtgen
Model	W150CFI
Serial Number	08130123
Туре	Road Milling Machine
Date Of Inspection	5/20/2021
Location of Inspection	JJ Kane Auctioneers; 1402 Conshohocken Rd, Plymouth Meeting, PA,19462
Attachment(s)/ Accessory(s)	None
Enclosed Cab	No
Cab A/C	No
Cab A/C Condition	N/A
Cab Heat	No
Cab Heat Condition	N/A
Keyless Start	No
Hours	620




Aspen Field Services

Job #: 30626 / Serial #: 08130123

For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd

Inspection Details Cont'd	
Active Warnings None	
Hydraulic Cylinders	Good Condition
Front Left Track Condition	Good Condition
Front Left Track Brand	Not Available
Front Left Track Sprocket	Good Condition
Front Left Track Rollers	Good Condition
Front Left Track Idler	Good Condition
Back Left Track Condition	Good Condition
Back Left Track Brand	Not Available
Back Left Track Sprocket	Good Condition
Back Left Track Rollers	Good Condition
Back Left Track Idler	Good Condition
Front Right Track Condition	Good Condition
Front Right Track Brand	Not Available
Front Right Track Sprocket	Good Condition
Front Right Track Rollers	Good Condition
Front Right Track Idler	Good Condition
Back Right Track Condition	Good Condition
Back Right Track Brand	Not Available
Back right Track Sprocket	Good Condition
Back Right Track Rollers	Good Condition
Back Right Track Idler	Good Condition
Operational Test	Passed - Operational
Mirrors	Good Condition
Backup Camera	Yes
Intake Screen	Good Condition
Muffler	Good Condition
Lights	See Notes
Engine Compartment	See Notes
Operator Seat	Tear
Cab Steps	Good Condition





Aspen Field Services

Job #: 30626 / Serial #: 08130123 For more information, visit: wellsfargo.com/equipmentseller

Comments

The operator was not able to turn on the lights, which prevented us from verifying their operations. The engine compartment was not accessible from the ground.