



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15785544 - 2021 Tigercat 724G Wheel Feller Buncher



Item Details:

- Features: Air Conditioner, Fire Suppression System, Rear View Camera, Joystick Steering, Tier 4, Requires Diesel Exhaust Fluid, 2021 Tigercat DW5502 38 in Feller Buncher
- Meter Reading: 4,838 Hours
- Serial # : 7244654
- Inspection Completed: 9/11/26

Shipping Details:

- Location Tennessee (Nashville area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	7244654	
Hour Meter / Odometer	4838 hrs	
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders		
Hand Rails		
Glass		


Exterior Lights	Operational	
v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		

Safety

Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station

Item	Assessment	Photo
Seats/Armrests		
Mirrors		
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	

Engine Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational, see photos light stays on	
Gauges	Operational	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted. Engine RPM switch inoperable	
Control Station #1		
Control Station #2		
Control Station #3		

Control Station #4		
Control Station #5		
Control Station #6		
Control Station #7		
Control Station #8		
Control Station #9		
Control Station #10		

Control Station #11		
Control Station #12		
Control Station #13		

Engine		
Item	Assessment	Photo
Engine	US EPA Label not legible Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Operational	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	

Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	After jump starting, the engine ran.	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		

v2 Engine # 4



Drivetrain

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Rear Drive Axle	★★☆☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics

Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆ Unable to visualize	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Excavator_2 # 1		
Excavator_2 # 2		

Excavator_2 # 3		
Excavator_2 # 4		
Excavator_2 # 5		
Excavator_2 # 6		
Excavator_2 # 7		
Excavator_2 # 8		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Bunching Head Frame	★ ★ ★ ☆	
Gathering Arms	★ ★ ★ ☆	
Tilt Cylinders	★ ★ ★ ☆	
Arm Cylinders	★ ★ ★ ☆	
Cutting Blade	★ ★ ★ ☆	
Boom Condition	★ ★ ★ ☆	

Boom Base Pin and Bushings	★★★★☆	
Bottom Covers		
Limited Function Check	The main components were operational in a limited check.	
Articulating Center Pins	★★★★☆	
Brake Type	Hydraulic	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Tire Brands	Unable to read tire information, scrubbed off	
Left Front Tire		
Left Rear Tire		

Right Rear Tire	Low	
Right Front Tire		
Wheel Condition	★★★★☆	
Wheel Studs, Nuts, Lugs	★★★★☆	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		

Chassis #5		
Chassis #6		
Chassis #7		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved

2021 TIGERCAT 724G

UNIT: 7244654

Current Location: Wells Fargo (IMS), Lebanon, TN 37090, 555-555-5555



UNIT SPECS

Customer	Wells Fargo (IMS)
----------	-------------------

RECONDITIONING

Engine RPM switch: inoperable	\$350	Paint: damaged	\$2,000
2 Warnings on dash	\$4,500	Jump-Started - Replace Batteries	\$1,500
Right Rear Tire: Low air	\$350		

Total	\$8,700
-------	---------

















