



2023 CAT D 1

UNIT: CAT000D1TXKL04279

[Download Reconditioning Printout](#)









UNIT SPECS

Customer

Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)



Please call Pickup Support for location information
Humble, TX 77396

GENERAL APPEARANCE

Serial Number / VIN
CAT000D1TXKL04279



Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid

☐ ☐

Paint

No visible damage

☐ ☐

Cab/Canopy Overhead Structural Framework

No visible damage

☐ ☐

Steps/Ladders

No visible damage or missing components

Rating:

Good

☐ ☐

Hand Rails

No visible damage or missing components

☐ ☐

Exterior Lights

All lights operational

☐ ☐

Body Panels

No visible damage or missing components

☐ ☐

Year

2023

☐ ☐

Make

Cat

☐ ☐

Model

D 1

☐ ☐

SAFETY

Travel Alarm

Operational

☐ ☐

Horn

Operational

☐ ☐

Seat Belts
Operational



Current Safety Manual

No



Current Operator/Maintenance Manual

No



CONTROL STATION

Cab Doors

No visible damage or missing components



Hydraulic Controls

Rating:

Good



Drivetrain Controls

Rating:

Good



Warning Lights

Operational



Gauges

Operational



Rear View Camera

Camera operates as intended



Air Conditioner

Operational



Heater

Operational



Seat/Armrests

No visible damage or missing components



Glass

No visible damage or missing components



Steering Controls

Rating:

Good



Dash Console

Rating:

Good



Engine Oil Pressure

No oil pressure indicator



Hour Meter (Pre-inspection)

59.4 hrs



Hour Meter

58 hrs



Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control



ENGINE

A/C Compressor

Operational



Starter

Operational



Exhaust System

No visible damage or missing components



Radiator

Rating:

Good



Oil Leaks

No dripping leaks



Fuel Leaks

No dripping leaks



Cooling System Leaks

No dripping leaks



Limited Function Check (Engine)

The engine started and ran.



Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure



Engine

Requires Diesel Exhaust Fluid



DRIVETRAIN

Service Brakes

Rating:

Good



Drive Motors

Rating:

Good



Final Drives

Rating:

Good



Limited Function Check (Drivetrain-Track)

The drivetrain was operational without a load.



Transmission

Rating:

Good



HYDRAULICS

Pumps (Hydraulics)

Rating:

Good



Valves

Rating:

Good



Hydraulic Tank

Rating:

Good



Hoses (Hydraulics)

Rating:

Good



Blade Lift Cylinders

Rating:

Good



Blade Angle Cylinders

Rating:

Good



Blade Tilt Cylinders

Rating:

Good



Limited Function Check (Hydraulics)

The hydraulic system was operational.



CHASSIS

Frame Condition

Rating:

Good



Belly Pans

Rating:

Good



Tilt Linkage Pins and Bushings

Rating:

Good



Angle Linkage Pins and Bushings

Rating:

Good



Limited Function Check (dozer)

The main components were operational in a limited check.



Front Attachment

124 in Wide PAT Blade, Cat



Blade Condition

Rating:

Good



UNDERCARRIAGE

Left Roller Frame

Rating:

Good



Left Track Links

New 59 hrs



Left Track Bushings

New 59 hrs



Left Carrier Rollers

New 59 hrs



Left Sprocket

Rating:

Good



Right Roller Frame

Rating:

Good



Right Track Tensioner

Rating:

Good

☐ ☐

Right Grouser Height

Ew 59 hrs

☐ ☐

Right Track Links

New 59 hrs

☐ ☐

Right Track Bushings

New 59 hrs

☐ ☐

Right Carrier Rollers

New 59 hrs

☐ ☐

Right Sprocket

New 59 hrs

Rating:

Good

☐ ☐

Left Track Pads

25 in Wide Single Grouser

Rating:

Good

☐ ☐

Right Track Pads

25 in Wide Single Grouser

Rating:

Good

☐ ☐

Left Bottom Rollers

New 59 hrs

☐ ☐

Left Idler

New 59 hrs

☐ ☐

Right Bottom Rollers

New 59 hrs

☐ ☐

Right Idler

New 59 hrs

☐ ☐

LOGISTICS INFORMATION

Shipping Dimensions

13 ft 6 in Long x 10 ft 4 in Wide x 11 ft Tall 0.0 lb Shipping Weight

☐ ☐

General Shipping Information

Yes: Does this Unit Run? No: If self propelled, does the unit travel? No: Is the unit taller than 12'? No: Is the unit wider than 8'6"? No: Inflated Tires - item can roll? No: Noticeable fluid leaks?

☐ ☐

Road Related Shipping Info

The lights and brakes were not operationally checked, Yes: Lights Operate?

☐ ☐

RECONDITIONING