

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipmentseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvig.com

Make:	Bobcat	Type:	Skid Steer	Inspector:	GP
Model:	S770	Hours:	1941	Inspection Date:	11/7/2024
SN:	AT5A17176	Year:	2021		

## SPECIFICATIONS

ROPS:	<b>Yes</b>	Hours:	<b>1941</b>			
Enclosed Cab:	<b>No</b>	Cab Heat:	<b>No</b>	Cab A/C:	<b>No</b>	Controls: <b>Selectable Joystick Controls</b>
Attachment on Machine:	80" Bucket					
Additional Attachments:	N/A					
2-Speed:	<b>Yes</b>	Engine MFR:	<b>DOOSAN</b>	Tires		
High Flow Hydraulics - Sticker:	<b>Yes</b>	Power Bob-Tach:	<b>Yes</b>	Keyless Start:	<b>No</b>	
Backup Camera:	<b>No</b>	Ride Control:	<b>No</b>	Deluxe Instrumentation:	<b>No</b>	
Hydraulic X-Change:	<b>No</b>					
Comments and Defects:	<b>INTERIOR DIRTY,</b>					

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

FRONT AXLE	
Make: POWER KING Part #: RIM GUARD Measure: 2 / 32 Condition: POOR Tread Remaining: Under 50% Fault:	Make: POWER KING Part #: RIM GUARD Measure: 0 / 32 Condition: POOR Tread Remaining: Under 50% Fault:

REAR AXLE	
Make: POWER KING Part #: RIM GUARD Measure: 6 / 32 Condition: POOR Tread Remaining: Under 50% Fault:	Make: POWER KING Part #: RIM GUARD Measure: 3 / 32 Condition: POOR Tread Remaining: Under 50% Fault:

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipmentseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

## CONDITION REPORT

	Check	Comments / Deficiencies
X	Visual Inspection	INTERIOR DIRTY
✓	Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓	Lift Cylinders	NO LEAKS
✓	Tilt Cylinders	NO LEAKS
✓	Boom Arms Operations	WORKING
✓	Seat	GOOD CONDITION
✓	Tailgate Lights	GOOD CONDITION
✓	Working Lights	GOOD CONDITION
N/A	Front Door	
✓	Rear and Top Window	NO DAMAGES
N/A	Side Glass Complete	
✓	Boom Arms Damages	NO DAMAGES
✓	Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓	Mufflers	GOOD CONDITION
✓	ROPS Condition	GOOD CONDITION
✓	Power Bob-Tach Condition	OPERATIONAL
N/A	Cab A-C Condition	
N/A	Cab Heat Condition	
✓	Intake Screen	GOOD CONDITION
X	Eng. Compartment	OIL LEAK AROUND BREATHER AREA
N/A	Hydraulic X-Change Condition	
✓	Customer Decals Visible on Unit	NO
✓	Error Codes	
X	Front Right Tire Depth Percentage	FRONT RIGHT TIRE UNDER 50%
X	Front Left Tire Depth Percentage	FRONT LEFT TIRE UNDER 50%
X	Rear Right Tire Depth Percentage	REAR RIGHT TIRE UNDER 50%
X	Rear Left Tire Depth Percentage	REAR LEFT TIRE UNDER 50%
X	Condition Report	SELECTABLE JOY STICK AND HI FLOW DECALS TORN - NOT LEGIBLE

PHOTOS



Front Left



Front Right



Rear



Seating / Interior

PHOTOS



PHOTOS



PHOTOS



PHOTOS





PHOTOS



PHOTOS



PHOTOS

