

2018 ROBOTEC 960

UNIT: 140756-1-1

[Download Reconditioning Printout](#)







UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)



Please call Pickup Support for location information
South Vienna, OH 45369

GENERAL APPEARANCE

UID 140756-1-1 **Hour Meter/Odometer** 2589 hrs

CONTROL STATION

Seat Operational **Hydraulic Controls** Good

HYDRAULICS

Valves Good **Hoses (Hydraulics)** Good

Swing Motor Condition Rating Good **Hydraulic Center Swivel Condition** Good

Boom Lift Cylinder Condition Good **Stick Cylinder** Good

Grapple Cylinder
Rotobec 4552HD-B-BF3-CBB-A Log Grapple

Grapple Rotation Motor Good

CHASSIS

Grapple Condition Good

Boom Condition Good

Stick Condition Good

Boom Base Pin and Bushings Rating Good

Pins/Bushings Good

Pin and Bushings Stick to Coupler Rating Good

Turntable Bearing Good

Limited Function Check (Chassis)
The main components were operational in a limited check.

Grapple Arm Pins and Bushings Good

TRAILER

Brake Lines/Hoses Good

Limited Function Check (Rubber Tire)
The engine started and ran.

Lights/Wiring Condition Operational

Frame Rails/Main Beams Condition
self contained stabilizers

Landing Gear/Tongue Jack Condition Good

Stabilizer Jack Cylinders Condition Good

RECONDITIONING

right Front Catwalk Damaged \$1,500

Seat Damage/Torn \$350

Total \$1,850

“ 33 ft Long x 8 ft Wide x 12 ft Tall
“ Too Cold To Test A/C