



## Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/PygPzt2ZABFqPvdc8/full\\_report\\_0033728\\_PygPzt2ZABFqPvdc8.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/PygPzt2ZABFqPvdc8/full_report_0033728_PygPzt2ZABFqPvdc8.pdf?view)

**NOTE:** By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2014
Make	Manitou
Model	MHT 10120
Serial Number	765393
Type	Telehandler
Inspection Date	09/10/2021
Location of Business	JJ Kane Auctioneers 135 Hwy 16 , Glendive, MT, 59330, USA
Attachment(s)/ Accessory(s)	None
Bent Forks	NA
Excessive Wear	NA
Mismatched	NA
Hours	4882
Enclosed Cab	Yes
Cab A/C	Yes
Cab A/C Condition	Good Condition



## Aspen Field Services

Job #: 33728 /

Serial #: 765393

For more information, visit:

[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)

MANITOU MHT 10120

### Inspection Details Cont'd

Cab Heat	Yes
Cab Heat Condition	Good Condition
Controls	Standard
Seat	Good Condition
Interior	Good Condition
Cab Glass	Yes
Cab Glass Condition	Good Condition
Front Left Tire Condition	Good Condition
Front Left Tire Brand	Camso Loadmaster
Front Left Tire Part Number	17.5-25 L2
Front Left Tire Tread Depth	30/32
Front Right Tire Condition	Good Condition
Front Right Tire Brand	Camso Loadmaster
Front Right Tire Part Number	17.5-25 L2
Front Right Tire Tread Depth	32.76/32
Back Left Tire Condition	Good Condition
Back Left Tire Brand	Camso Loadmaster
Back Left Tire Part Number	17.5-25 L2
Back Left Tire Tread Depth	29/32
Back Right Tire Condition	Good Condition
Back Right Tire Brand	Camso Loadmaster
Back Right Tire Part Number	17.5-25 L2
Back Right Tire Tread Depth	32.76/32
Mismatched Tires	No
Engine Panel	Good Condition
Engine Compartment	Dirty
Engine Manufacturer	Mercedes Benz
Muffler	Good Condition
Intake Screen	Good Condition
Boom Arm	Good Condition

### Inspection Details Cont'd



## Aspen Field Services

Job #: 33728 /

Serial #: 765393

For more information, visit:

[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)

MANITOU MHT 10120

Lift Cylinder	Good Condition
Tilt Cylinder	Good Condition
Angle Cylinders	Good Condition
Hydraulic Hoses	Good Condition
Stabilizers Cylinders	None
Working Lights	Not Operational
Tailgate Lights	Good Condition
Active Warnings	Low Battery Level
Operations Test	Failed Most Movements
Comments	The equipment has a low battery voltage. The unit is able to drive forwards and backwards, however, the hydraulic system was not operational. Boom Arm Light is not operational. Working Lights on the cab are not operational. A piece of the Cab A/C and Heat vent is missing. The enclosure latch is damaged. The engine has oil leaks. Front right wheel seal possibly leaking. Engine door has a makeshift latch.