



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 10/30/2020 | | JDHN8580 |

INSPECTOR: 5932  
 INSPECTION ID  
 129683

Year 2018 Make GRECH  
 Model GM40 VIN 3ALACXFCXJDHN8580

SPECIFICATION WORKSHEET

<b>Interior Options</b>	
Interior Color:	BLACK

<b>Steering Options</b>	
Power Steering?:	Yes

<b>Engine Options A</b>	
Eng Make:	CUMMINS
Eng Model:	ISB
Eng Serial:	74089101
Eng HP:	425
Cruise:	Yes
Clean air idle:	Yes

<b>Overall Condition</b>	
Overall Length:	40'
Overall Height:	10'
Overall Width:	8'3"

<b>Engine Options B</b>	
Odometer:	102946
Hub odometer:	NA
ECU HP:	500
ECU Miles:	102951
Eng Hours:	2900

<b>Miscellaneous</b>	
Seating Capacity:	37
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	No
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	6
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additional comments:	NA

<b>Engine Options C</b>	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	50 @ 2

<b>Exterior Options A</b>	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	BLACK

<b>Axle / Susp Options</b>	
WheelBase (In):	187
Rear Ratio:	4.56
F Axle (lbs):	12,000
R Axle (lbs):	17,500
GVWR (lbs):	29,500
Suspension:	AIR RIDE
Tag Axle Capacity:	NA
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	No
Tag Axle Unloading System:	No
Front Susp. Kneeling System:	No

<b>Transmission Options</b>	
Trans Make:	MERCEDES BENZ
Trans Model:	ALLISON 2500
Trans Speed:	12



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 10/30/2020 | | JDHN8580 |







INSPECTOR: 5932  
 INSPECTION ID  
 129683

Brakes Options	
ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes			
Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
			(3)
			(4)
			(5)
			(6)

Tires [Front]	
Size:	295/75 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]	
Size:	295/75 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1
RIGHT	16 / 32nd HIGHWAY / V 	8 / 32nd LUG / R1 
FRONT		9 / 32nd LUG / R1 
LEFT	 13 / 32nd HIGHWAY / V	8 / 32nd LUG / R1 
		11 / 32nd LUG / R1 

Brake Legend
BD = DRUM HAS MORE THAN 1/16 INCH LIP CL = CRACKED LINING LS = LEAKING SEAL(S)
Tire Legend
C = CUT D = DRY ROT F = FLAT M = MISMATCHED TIRES/CASING MA = MISMATCHED AXLES (FRONT vs. REAR) V = VIRGIN W = IRREGULAR WEAR R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES
Tread Legend
H = HIGHWAY L = LUG



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 10/30/2020 | | JDHN8580 |

INSPECTOR: 5932  
 INSPECTION ID  
 129683

CONDITION REPORT

Engine Compartment Area		COMMENTS	
Operational Test		COMMENTS	
In Cab Inspection		COMMENTS	
X	Windshield, Door & Any Other Glass	WINDSHIELD CHIPPED	
Outside Inspection		COMMENTS	
X	Paint Condition & Physical Damage	BODY & PAINT DAMAGE	
Under Vehicle Inspection		COMMENTS	
Tires/Wheels/Brakes		COMMENTS	
Additional Services	Requested	Status	Comments



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
362 - Wells Fargo Equipment Management  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
10/30/2020 | | JDHN8580 |

INSPECTOR: 5932  
INSPECTION ID  
129683

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Windshield, Door & Any Other Glass	X   WINDSHIELD CHIPPED
Paint Condition & Physical Damage	X   BODY & PAINT DAMAGE
HOOD	DAMAGED
RIGHT FENDER	DAMAGED
RIGHT SIDE PANEL	DAMAGED
LEFT SIDE PANEL	DAMAGED
REAR CAP	DAMAGED (PAINT)
REAR BUMPER	DAMAGED

**COMMENTS:**  
THE BUS WAS INSPECTED AT NATION'S IN NORWALK. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE WINDSHIELD, RIGHT AND LEFT SIDE PANELS, REAR CAP AND THE REAR BUMPER.



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 10/30/2020 | | JDHN8580 |

INSPECTOR: 5932  
 INSPECTION ID  
 129683



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT  
 DOOR



COMPLETE DRIVERS SEAT



ODOMETER



DASH HOUR METER



DEKRA Services Inc.  
Customer Service 770-257-0107

**BUS**

CLIENT  
362 - Wells Fargo Equipment Management  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
10/30/2020 | | JDHN8580 |

INSPECTOR: 5932  
INSPECTION ID  
129683



INSIDE OF BUS, FRONT TO BACK



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT



FLOOR OF BUS, BACK TO FRONT



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT  
RIGHT SIDE



ENGINE COMPARTMENT LEFT  
SIDE



INSIDE STORAGE  
COMPARTMENTS



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



DEKRA Services Inc.  
Customer Service 770-257-0107

**BUS**

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

10/30/2020

FLEET NAME

VIN (LAST 8)

PO NUMBER

JDHN8580

INSPECTOR: 5932

INSPECTION ID

129683



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 15



ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 18



ADDITIONAL 19



ADDITIONAL 20

