

INSPECTION SUMMARY

2015 Capello Quaser R12 Corn Head
SN 11149
Attica, Indiana

May 18, 2020

Equipment Inspection Location: 3325 North US High-Way 41, Attica, Indiana

Inspection Date: May 14, 2020

Description: 2015 Capello Quaser R12 Corn Head

Serial Number: 11149

Hours: N/A

General Description: 12-30" Rows, Hydraulic Folding Wings, 16" Dia. Auger, Poly Folding Snouts, Headsight Insight Height Sensor

Mechanical Condition: Fair Condition. Not able to see function. Gathering chains, knives, and auger showing normal wear. Missing end row snouts. Otherwise appears to be complete.

Exterior Condition: Fair to Average Condition. Paint chips and surface rust on frame and backside of head. Manual storage tube cap is cracked and has hole.

Overall Condition: Fair Condition. End snouts are missing. Various paint chips and surface rust on frame and back of head.

Maintenance: No maintenance records provided at the time of inspection.

Estimate of Repairs: Lessee estimated approx. \$300-\$400 to replace each end row snout.

Inspector Notes: Needs end row snouts. Otherwise looks to be complete with normal wear.

EQUIPMENT INSPECTION

2015 Capello Quaser R12 Corn Head

SN 11149
Attica, Indiana

May 18, 2020

Representative Pictures





EQUIPMENT INSPECTION

2015 Capello Quaser R12 Corn Head

SN 11149
Attica, Indiana

May 18, 2020

Representative Pictures



EQUIPMENT INSPECTION

2015 Capello Quaser R12 Corn Head

SN 11149
Attica, Indiana

May 18, 2020

Representative Pictures



EQUIPMENT INSPECTION

2015 Capello Quaser R12 Corn Head

SN 11149
Attica, Indiana

May 18, 2020

Representative Pictures

