



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSPECTOR: 5932
INSPECTION ID
130101

INSP DATE | VIN (LAST 8) | PO NUMBER
11/03/2020 | FW067286 |

Year | Model | 2015 | Make | VIN | MCI
J4500

2MG3JM8A8FW067286

SPECIFICATION WORKSHEET

Interior Options		Steering Options	
Interior Color:	BLACK	Power Steering?:	Yes

Engine Options A		Overall Condition	
Eng Make:	DETROIT	Overall Length:	45'
Eng Model:	DD13	Overall Height:	140"
Eng Serial:	471934S0338137	Overall Width:	102"
Eng HP:	282		
Cruise:	Yes		
Clean air idle:	Yes		

Engine Options B		Miscellaneous	
Odometer:	166350	Seating Capacity:	50
Hub odometer:	NA	Electronic Engine Controls:	Yes
ECU HP:	500	Full Gauge Package:	Yes
ECU Miles:	166500	Wraparound Dash:	Yes
Eng Hours:	7867	Power Mirrors:	Yes

Engine Options C		Tilt / Telescopic Steering Wheel:	
Eng Brake:	JAKE	AirRide Driver's Seat:	Yes
Fuel:	DIESEL	Restroom:	Yes
FT1 Capac (Gal):	192	PA System:	Yes

Exterior Options A		Audio - Video System:	
Air Horns:	NONE	Number of Video Monitors:	6
Mirrors:	DUAL POWER	Multi-Disc CD Changer:	Yes
Exterior Color:	WHITE	Individual multi-Channel Audio System:	No

Axle / Susp Options		Global Positioning System:	
WheelBase (In):	315	In Motion Satellite TV System:	No
Rear Ratio:	2.42	Road Viewing Monitor System:	Yes
F Axle (lbs):	16,500	Wheelchair Lift:	No
R Axle (lbs):	16,500	Underfloor Storage with Lift:	No
GVWR (lbs):	33,000	Parcel Rack Storage with Lift:	No
Suspension:	AIR RIDE	Traction Control:	Yes
Tag Axle Capacity:	23,000	Power Windshield Sun Visors:	Yes
Rear Axle Model:	NA	Tour Guide Seat:	No
Independent Front Suspension:	Yes	Other:	NA
Full Coach Raise and Lowering Susp.:	Yes	Was Unit driven In ?:	Yes
Tag Axle Unloading System:	Yes	Did Unit need to be jump started ?:	No
Front Susp. Kneeling System:	Yes	Was Unit towed in ?:	No

Transmission Options		Did Unit start and run ?:	
Trans Make:	ALLISON	Unit Condition:	GOOD
Trans Model:	3000/4000	If Unit is not driveable or will not start, Explain:	NA
Trans Speed:	6	Any extra options or features not listed on front page and any additional comments:	NA



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 11/03/2020 VIN (LAST 8) FW067286 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
130101

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Brakes

Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		16 / 32nd LUG / R1	12 / 32nd LUG / R1
RIGHT	17 / 32nd HIGHWAY / V 	 	 
FRONT		16 / 32nd LUG / R1	/ 32nd /
LEFT	 17 / 32nd HIGHWAY / V	 	 
		16 / 32nd LUG / R1	15 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
11/03/2020	FW067286	

INSPECTOR: 5932
INSPECTION ID
130101

CONDITION REPORT

Engine Compartment Area	COMMENTS
Operational Test	COMMENTS
In Cab Inspection	COMMENTS
Outside Inspection	COMMENTS
Under Vehicle Inspection	COMMENTS
Tires/Wheels/Brakes	COMMENTS

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
11/03/2020	FW067286	

INSPECTOR: 5932
INSPECTION ID
130101

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
LEFT SIDE VENT DOOR	DAMAGED
ENGINE LID	DAMAGED
CENTER REAR BUMPER	DAMAGED
RIGHT REAR OUTER WHEEL	DAMAGED

COMMENTS:
THE BUS WAS INSPECTED AT MCI IN HAYWARD. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE LEFT SIDE VENT DOOR, ENGINE LID, REAR BUMPER AND THE RIGHT OUTER WHEEL.




DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 11/03/2020 VIN (LAST 8) FW067286 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
130101



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



DASH HOUR METER



DEKRA Services Inc.
Customer Service 770-257-0107


BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
11/03/2020	FW067286	

INSPECTOR: 5932
INSPECTION ID
130101



INSIDE OF BUS, FRONT TO BACK



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT



FLOOR OF BUS, BACK TO FRONT



INSIDE RESTROOM #1



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER




ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



J PRO SCREEN



ADDITIONAL 1



ADDITIONAL 2



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 11/03/2020 VIN (LAST 8) FW067286 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
130101



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6

JPRO		DIAGNOSTIC REPORT	
Vehicle Information			
Make	Model	Year	Color
Engine Information			
Engine Type	Engine Size	Engine Code	Engine Serial
Transmission Information			
Transmission Type	Transmission Size	Transmission Code	Transmission Serial
Test Results			
Test Name	Test Result	Test Status	Test Date
Page 1 of 1			

ADDITIONAL 7

JPRO		DIAGNOSTIC REPORT	
Vehicle Information			
Make	Model	Year	Color
Engine Information			
Engine Type	Engine Size	Engine Code	Engine Serial
Transmission Information			
Transmission Type	Transmission Size	Transmission Code	Transmission Serial
Test Results			
Test Name	Test Result	Test Status	Test Date
Page 1 of 1			

ADDITIONAL 8

JPRO		DIAGNOSTIC REPORT	
Vehicle Information			
Make	Model	Year	Color
Engine Information			
Engine Type	Engine Size	Engine Code	Engine Serial
Transmission Information			
Transmission Type	Transmission Size	Transmission Code	Transmission Serial
Test Results			
Test Name	Test Result	Test Status	Test Date
Page 1 of 1			

ADDITIONAL 9