

2016 CAPACITY SABRE5

UNIT: 4LMSF211XGL030947

[Download Reconditioning Printout](#)







UNIT SPECS

Customer

Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)



Please call Pickup Support for location information
Humble, TX 77396

IDENTIFICATION

UID 4LMSF211XGL030947

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Axle Configuration 4x2

ENGINE

Engine Make Cummins

Engine Model ISB6.7

Engine Model 2 Diesel 200 hp

Engine Cylinders 6

Engine Displacement 6.7 L

EPA Label 2016 US EPA Label

A/C Compressor Compressor will not engage

A/C Compressor Rating Operational

Starter Operational

Radiator Good

Limited Function Check (Engine)
The engine started and ran.

CONTROL STATIONS

Air Conditioner Inoperable

Cab Suspension Type Air Ride Cab

Window Controllers Rating Both Manual

Steering Control Rating Good

Warning Lights Operational

Gear Selector Good

Hour Meter/Odometer 0 mi

Limited Function Check (Control Station)
The main components are in place and operational as noted.

CHASSIS

Wheel Base 118 in Wheelbase

Steer Axle Rating Good

Transmission Operational

Steering Components Rating Good

Power Take Off Rating Good

PTO Pump Rating Operational

Rear Drive Axle Good

Cab Suspension Air Bags Rating Good

Suspension Bushings Rating Good

Wheel Condition Rating Good

Steer Tire Measurements
Drum: B-L-D | Drum: B-R-D | Steel: T-L-D | Steel: T-R-D

Fuel System Operational

Oil Pressure
The gauge registers in the operating range. 20 PSI

Heater Not operationally checked

Window Controllers Good

Seat Belts Operational

Horn Electric horn operational

Gauges Operational

Brake Controls Operational

Engine Hours 2615.6 Engine hrs

PTO Configuration PTO

Transmission Type Allison Automatic Transmission

Transmission Rating Good

Power Take Off Operational

PTO Pump Good

Frame Condition Rating Good

Limited Function Check (Drivetrain - Truck)
The drivetrain was operational without a load.

Suspension Springs/Hangers Rating Good

Wheel Condition 11R22.5

Wheel Studs, Nuts, Lugs Good

Rear Drive Axle Tire Measurements

Drum: B-L-DIDrum: B-R-DISteel: T-LO-DISteel: T-LI-DISteel: T-RI-DISteel: T-RO-D

Limited Function Check (Brakes)

The service brakes are operational, The park brake is operational.

Hydraulic Tank

Good

Fifth Wheel

Hydraulic Lift 5th Wheel

RECONDITIONING

A/C Compressor - Will Not Engage

\$1,500



Total

\$1,500