



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/zpBAeQjHDhGekHE3/full_report_0025750_zpBAeQjHDhGekHE3.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Vermeer
Model	SC60TX
Serial Number	1VRY12055J1004354
Type	Stump Cutter
Inspection Date	11/18/2020
Location of Business	JJ Kane Auctioneers - 100 Liberty Rd , Villa Rica, GA, 30180
Operator Vision Shield	Polycarbonate
Engine MFR	Caterpillar
Gross Horsepower	60 hp
Broken or Missing Cutterwheel Teeth	Yes
Tooth Description	Yellow Jacket Cutter System
Cutterwheel Diameter without Teeth	23 "
Control Station Description	Swing out
Radio Remote Control	No



Aspen Field Services

Job #: 25750 /

Serial #: 1VRY12055J1004354

For more information, visit:

wellsfargo.com/equipmentseller

VERMEER SC60TX STUMP CUTTER

Inspection Details Cont'd	
Self-Propelled	Yes
Hours	278
Visual Inspection	Clean
Operational Test	Passed - Moved forward/back ward
Left Track Condition	Good Condition
Left Track Depth Measurement	8/32"
Right Track Condition	Good Condition
Right Track Depth Measurement	8/32"
Mismatched Tracks	No
Lift Cylinders	Could Not Be Accessed
Working Lights	None
Angle Cylinders	No Leaks
Intake Screen	Good Condition
Engine Compartment	Clean
Customer Decals Visible on Unit	No
Comments	

Inspection Details Cont'd
