



Item #5657084 - John Deere L340 Big Square Baler



Item Details:

- Features: 1000 PTO, Lunette Ring, 3 ft 11 in Wide x 3 ft High Bales, Push Bar Ejector, Auto Lube
- Meter Reading: Not Available
- Serial # : 1E0L340PEFF410309
- Inspection Completed: 10/21/21

Shipping Details:

- Location California (Kings County)
- Loading Dock Available: No

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Serial Number / VIN	1E0L340PEFF410309	
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Front Corner		

Picture, Right Rear Corner



Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
PTO Requirement	1000 rpm (20 spline), The driveshaft is not complete, There is no driveshaft with the unit	
Pickup Attachment	★★★★☆	
Feeder System	★★★★☆	
Plungerhead Guides and Bearings	★★★★☆	
Tie System	6	
Drive Belts/Pulleys, Chains and Sprockets	★★★★☆	
Monitor/Control Unit	POC was not available after inspection to see if this is here.	

Automatic Lube System	Yes	
Bale Accumulator	★★★☆☆ Yes	
Limited Function Check	The baler was not connected to a power source. This machine could not be operationally checked. Some of the ratings may be based on a static, visual inspection.	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		

Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
PTO Requirement	1000 rpm (20 spline), The driveshaft is not complete, There is no driveshaft with the unit	
Pickup Attachment	★★★★☆	

Precutter/Chopping System	★★★★☆ Yes, 12 knives	
Roller Condition	★★★★☆	
Bale Chamber	★★★★☆	
Rear Gate	★★★★☆	
Bale Push Bar	★★★★☆	
Drive Chains/Sprockets	★★★★☆	
Automatic Lube System	Yes	
Limited Function Check	The baler was not connected to a power source. This machine could not be operationally checked. Some of the ratings may be based on a static, visual inspection.	
Chassis #1		

Frame Rails/ Main Beams Condition	★★★★☆	
Cross Members	★★★★☆	
Tongue/ Hitch Condition	★★★★☆ No visible damage, Lunette ring	
Springs/Hangers Condition	★★★★☆	
Axle Condition	★★★★☆	
Tire Size	445/50/22.5 Front tires, 445/50/22.5 Rear tires, LF Yokohama, LR Michelin, RR Michelin, RF Yokohama	
Tire Condition		

Tread Depth (4 tires)	LF 7 mm, LR 14 mm, RR 14 mm, RF 19 mm	
Wheel Condition	★★★★☆	
Wheel Studs	★★★★☆	
Limited Function Check	The baler was not connected to a power source. This machine could not be operationally checked. Some of the ratings may be based on a static, visual inspection.	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Cylinder(s)	★★★★☆	
Cylinder Pins and Bushings	★★★★☆	
Limited Function Check	The hydraulic system could not be operationally checked.	

Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		
Hydraulics #7		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved