



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 08/06/2020 | | F2042800 |

INSPECTOR: 6046  
 INSPECTION ID  
 123279

Year 2015 Make VAN HOOL  
 Model TDX25 VIN YE2ZG11B4F2042800

SPECIFICATION WORKSHEET

|                         |       |
|-------------------------|-------|
| <b>Interior Options</b> |       |
| Interior Color:         | BLACK |

|                         |     |
|-------------------------|-----|
| <b>Steering Options</b> |     |
| Power Steering?:        | Yes |

|                         |         |
|-------------------------|---------|
| <b>Engine Options A</b> |         |
| Eng Make:               | DETROIT |
| Eng Model:              | DD-13   |
| Eng Serial:             | UNK     |
| Eng HP:                 | 425     |
| Cruise:                 | Yes     |
| Clean air idle:         | Yes     |

|                          |      |
|--------------------------|------|
| <b>Overall Condition</b> |      |
| Overall Length:          | 45'  |
| Overall Height:          | 170" |
| Overall Width:           | 102" |
|                          |      |
|                          |      |

|                         |        |
|-------------------------|--------|
| <b>Engine Options B</b> |        |
| Odometer:               | 176035 |
| Hub odometer:           | NA     |
| ECU HP:                 | 500    |
| ECU Miles:              | 175154 |
| Eng Hours:              | 8876   |

|                                                                                           |      |
|-------------------------------------------------------------------------------------------|------|
| <b>Miscellaneous</b>                                                                      |      |
| Seating Capacity:                                                                         | 72   |
| Electronic Engine Controls:                                                               | Yes  |
| Full Gauge Package:                                                                       | Yes  |
| Wraparound Dash:                                                                          | Yes  |
| Power Mirrors:                                                                            | Yes  |
| Tilt / Telescopic Steering Wheel:                                                         | Yes  |
| AirRide Driver's Seat:                                                                    | Yes  |
| Restroom:                                                                                 | Yes  |
| PA System:                                                                                | Yes  |
| Audio - Video System:                                                                     | Yes  |
| Number of Video Monitors:                                                                 | 7    |
| Multi-Disc CD Changer:                                                                    | Yes  |
| Individual multi-Channel Audio System:                                                    | No   |
| Global Positioning System:                                                                | Yes  |
| In Motion Satellite TV System:                                                            | Yes  |
| Road Viewing Monitor System:                                                              | Yes  |
| Wheelchair Lift:                                                                          | No   |
| Underfloor Storage with Lift:                                                             | No   |
| Parcel Rack Storage with Lift:                                                            | No   |
| Traction Control:                                                                         | Yes  |
| Power Windshield Sun Visors:                                                              | No   |
| Tour Guide Seat:                                                                          | No   |
| Other:                                                                                    | NA   |
| Was Unit driven In ?:                                                                     | Yes  |
| Did Unit need to be jump started ?:                                                       | No   |
| Was Unit towed in ?:                                                                      | No   |
| Did Unit start and run ?:                                                                 | Yes  |
| Unit Condition:                                                                           | GOOD |
| If Unit is not driveable or will not start, Explain:                                      | NA   |
| Any extra options or features not listed on front page and any additional comments:<br>NA |      |

|                         |        |
|-------------------------|--------|
| <b>Engine Options C</b> |        |
| Eng Brake:              | JAKE   |
| Fuel:                   | DIESEL |
| FT1 Capac (Gal):        | 216    |

|                           |            |
|---------------------------|------------|
| <b>Exterior Options A</b> |            |
| Air Horns:                | NONE       |
| Mirrors:                  | DUAL POWER |
| Exterior Color:           | WHITE      |

|                                      |          |
|--------------------------------------|----------|
| <b>Axle / Susp Options</b>           |          |
| WheelBase (In):                      | 300      |
| Rear Ratio:                          | 4.25     |
| F Axle (lbs):                        | 18180    |
| R Axle (lbs):                        | 18180    |
| GVWR (lbs):                          | 62000    |
| Suspension:                          | AIR RIDE |
| Tag Axle Capacity:                   | 27575    |
| Rear Axle Model:                     | UNK      |
| Independent Front Suspension:        | Yes      |
| Full Coach Raise and Lowering Susp.: | No       |
| Tag Axle Unloading System:           | No       |
| Front Susp. Kneeling System:         | Yes      |

|                             |         |
|-----------------------------|---------|
| <b>Transmission Options</b> |         |
| Trans Make:                 | ALLISON |
| Trans Model:                | UNK     |
| Trans Speed:                | 6       |



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 08/06/2020 | | F2042800 |

INSPECTOR: 6046  
 INSPECTION ID  
 123279

| Brakes Options |                  |
|----------------|------------------|
| ABS:           | YES              |
| HYD:           | NO               |
| AIR:           | YES              |
| DISK:          | YES              |
| DRUM:          | NO               |
| Brake Plates:  | FRONT N / REAR N |

| Brakes             |     |     |     |
|--------------------|-----|-----|-----|
| Steer Axle Brakes: | 60% | 60% | (1) |
| Drive Axle Brakes: | 70% | 70% | (2) |
|                    | 70% | 70% | (3) |
|                    |     |     | (4) |
|                    |     |     | (5) |
|                    |     |     | (6) |

| Tires [Front] |              |
|---------------|--------------|
| Size:         | 315/80 R22.5 |
| Wheels:       | ALUMINUM     |
| Detail:       |              |

| Tires [Rear] |              |
|--------------|--------------|
| Size:        | 315/80 R22.5 |
| Wheels:      | ALUMINUM     |
| Detail:      |              |

|       | STEER AXLE               | DRIVE AXLE #1         | DRIVE AXLE #2         |
|-------|--------------------------|-----------------------|-----------------------|
| RIGHT | 12 / 32nd<br>HIGHWAY / V | 14 / 32nd<br>LUG / R1 | 10 / 32nd<br>LUG / R1 |
|       |                          |                       |                       |
| FRONT |                          | 13 / 32nd<br>LUG / R1 | / 32nd<br>/           |
|       |                          | 13 / 32nd<br>LUG / R1 | / 32nd<br>/           |
| LEFT  | 12 / 32nd<br>HIGHWAY / V |                       |                       |
|       |                          | 14 / 32nd<br>LUG / R1 | 10 / 32nd<br>LUG / R1 |

| Brake Legend                                                                                                                                                                             |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| BD = DRUM HAS MORE THAN 1/16 INCH LIP<br>CL = CRACKED LINING<br>LS = LEAKING SEAL(S)                                                                                                     |
| Tire Legend                                                                                                                                                                              |
| C = CUT D = DRY ROT F = FLAT<br>M = MISMATCHED TIRES/CASING<br>MA = MISMATCHED AXLES (FRONT vs.<br>REAR)<br>V = VIRGIN W = IRREGULAR WEAR<br>R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES |
| Tread Legend                                                                                                                                                                             |
| H = HIGHWAY L = LUG                                                                                                                                                                      |



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 08/06/2020 | | F2042800 |

INSPECTOR: 6046  
 INSPECTION ID  
 123279

CONDITION REPORT

| Engine Compartment Area  |                                          | COMMENTS |
|--------------------------|------------------------------------------|----------|
| OK                       | Fan Assembly, Shroud & Radiator          |          |
| OK                       | Hose Condition                           |          |
| OK                       | Record Coolant Protection Level          |          |
| OK                       | Oil in Cooling System                    |          |
| OK                       | Coolant DCA Level                        |          |
| OK                       | Coolant Level                            |          |
| OK                       | Power/Manual Steering Fluid Level        |          |
| OK                       | Clutch Master Cylinder Fluid Level       |          |
| OK                       | Brake Fluid Level                        |          |
| OK                       | Engine Oil Level                         |          |
| OK                       | Oil, Coolant and Other Fluid Leaks       |          |
| OK                       | Belt, Alignment, Condition & Adjustment  |          |
| OK                       | Belt & Engine Driven Components          |          |
| OK                       | Exhaust & Intake Systems                 |          |
| OK                       | Visible Inspection of Starter            |          |
| N/A                      | Other                                    |          |
| Operational Test         |                                          | COMMENTS |
| OK                       | Batteries - Capable of Starting Engine   |          |
| OK                       | Starter Condition                        |          |
| OK                       | Steering Free Play                       |          |
| OK                       | Clutch & Clutch Brake                    |          |
| OK                       | Transmission Shifts                      |          |
| OK                       | Brakes & Parking Brakes                  |          |
| OK                       | Throttle                                 |          |
| OK                       | Engine Brake                             |          |
| OK                       | Air Pressure Build Up                    |          |
| OK                       | Governed Air Pressure (psi)              |          |
| OK                       | Low Air Warning                          |          |
| OK                       | Gauges                                   |          |
| OK                       | Engine Warning System                    |          |
| OK                       | Seat Belts                               |          |
| OK                       | HVAC System                              |          |
| OK                       | Record A/C Temperature                   |          |
| OK                       | Windshield Wipers & Washers              |          |
| OK                       | Horns                                    |          |
| OK                       | Door Locks & Latches                     |          |
| OK                       | Window Operation                         |          |
| N/A                      | Other                                    |          |
| In Cab Inspection        |                                          | COMMENTS |
| OK                       | Windshield, Door & Any Other Glass       |          |
| OK                       | Interior Condition/ Seats, Panels, Etc.  |          |
| OK                       | DOT Required Safety Equipment            |          |
| OK                       | Other                                    |          |
| Outside Inspection       |                                          | COMMENTS |
| OK                       | Paint Condition & Physical Damage        |          |
| OK                       | Mirrors                                  |          |
| OK                       | Lights and Reflectors                    |          |
| OK                       | Fuel Tank Mounting & Condition           |          |
| OK                       | Batteries & Battery Box                  |          |
| OK                       | Intake & Exhaust Mounting & Condition    |          |
| N/A                      | Other                                    |          |
| Under Vehicle Inspection |                                          | COMMENTS |
| OK                       | Kingpins/Steering Components             |          |
| OK                       | Engine/Transmission Mounts               |          |
| OK                       | Frame, Crossmembers, Fasteners           |          |
| OK                       | Cab Mounts                               |          |
| OK                       | Driveshafts, U-joints, Yokes             |          |
| OK                       | Hydraulic Brake Lines & Components       |          |
| OK                       | Brake Hoses for Chafing & Cracking       |          |
| OK                       | Air Brake Components                     |          |
| OK                       | Transmission & Differential Fluid Levels |          |
| OK                       | Transmission & Differential Leaks        |          |
| OK                       | Air Leaks                                |          |
| OK                       | Suspension Condition                     |          |
| OK                       | Other                                    |          |
| Tires/Wheels/Brakes      |                                          | COMMENTS |
| OK                       | Tires/Wheels                             |          |
| OK                       | Brakes                                   |          |

| Additional Services | Requested | Status | Comments |
|---------------------|-----------|--------|----------|
|---------------------|-----------|--------|----------|

**COMMENTS:**  
THE BUS WAS INSPECTED AT THE CUSTOMER'S SHOP AREA INSIDE. THE UNIT WAS IN THE PROCESS OF BEING SERVICED. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS NO DAMAGE TO THE EXTERIOR OR INTERIOR.



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 08/06/2020 | | F2042800 |

INSPECTOR: 6046  
 INSPECTION ID  
 123279



vin plate



Instrument Panel



LEFT SIDE FRONT



FRONT CENTER



RIGHT SIDE FRONT



RIGHT SIDE REAR



RIGHT REAR TIRE



REAR CENTER



LEFT SIDE REAR




LEFT REAR TIRE



ENTRY DOOR AREA



DRIVER SEAT



ODOMETER



INTERIOR FRONT TO REAR



INTERIOR REAR TO FRONT



UPPER FLOOR INTERIOR  
 FRONT TO



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

CLIENT  
 362 - Wells Fargo Equipment Management  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 08/06/2020 | | F2042800 |

INSPECTOR: 6046  
 INSPECTION ID  
 123279



UPPER FLOOR INTERIOR REAR TO F



LEFT STEER TIRE



RIGHT FRONT STEER TIRE



ENGINE 1



ENGINE COMPARTMENT RIGHT SIDE



ENGINE COMPARTMENT LEFT SIDE



FRONT STAIRS



REAR STAIRS

J PRO

J PRO 1


J PRO 2

J PRO 3

J PRO 4

J Pro 5

J PRO 6



J PRO SCREEN