





2019 K-TEC 1237

UNIT: KS03078

[Download Reconditioning Printout](#)



UNIT SPECS

LOCATION

Wells Fargo (IMS) 📍

Please call Pickup Support for location information
Davenport, FL 33897

GENERAL APPEARANCE

UID	KS03078	Make and Model Review	4 Tire
General Condition	Good		

CHASSIS

Hitch Condition (Structural) Rating	Good	Bowl Condition Rating	Good
Floor Rollers/Guides Rating	Good	Ejector Face Condition Rating	Good
Apron Condition Rating	Good	Push Block Rating	Good
Cutting Edges	Center Cutting Edge Broken/Damaged	Cutting Edges Rating	Poor
Tire Size(s)	Tire Size: 26.5R25 Tires		

RECONDITIONING

Cutting Edges - Center Edge Broken/Damaged	\$400
---	-------



Total	\$400
--------------	--------------

