



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
03/09/2021		5621	HC713784	

INSPECTOR: 5436

INSPECTION ID

137732

Year	2017	Make	PREVOST
Model	H3-45	VIN	2PCH33496HC713784

SPECIFICATION WORKSHEET

Interior Options Interior Color: BLACK	Steering Options Power Steering?: Yes
Engine Options A Eng Make: VOLVO Eng Model: D13M435P Eng Serial: 0131168165 Eng HP: 435 Cruise: Yes Clean air idle: No	Overall Condition Overall Length: 45 Overall Height: 12.4 Overall Width: 102
Engine Options B Odometer: 97969 Hub odometer: ECU HP: NOT LISTED ECU Miles: 97973 Eng Hours: 4776	Miscellaneous Seating Capacity: 56 Electronic Engine Controls: Yes Full Gauge Package: Yes Wraparound Dash: Yes Power Mirrors: Yes Tilt / Telescopic Steering Wheel: No AirRide Driver's Seat: Yes Restroom: Yes PA System: Yes Audio - Video System: Yes Number of Video Monitors: 5 Multi-Disc CD Changer: No Individual multi-Channel Audio System: Yes Global Positioning System: No In Motion Satellite TV System: No Road Viewing Monitor System: Yes Wheelchair Lift: No Underfloor Storage with Lift: Yes Parcel Rack Storage with Lift: No Traction Control: Yes Power Windshield Sun Visors: Yes Tour Guide Seat: No Other: Was Unit driven In?: Yes Did Unit need to be jump started?: No Was Unit towed in?: No Did Unit start and run?: Yes Unit Condition: GOOD
Engine Options C Eng Brake: JAKE Fuel: DIESEL FT1 Capac (Gal): NO TAG	Any extra options or features not listed on front page and any additional comments: DVD PLAYER-110V W/USB OUTLETS-WIFI
Exterior Options A Air Horns: SINGLE Mirrors: HEATED DUAL POWER Exterior Color: WHITE	
Axle / Susp Options WheelBase (In): 337 Rear Ratio: NA F Axle (lbs): 16500 R Axle (lbs): 22500 GVWR (lbs): 53000 Suspension: AIR RIDE Tag Axle Capacity: 14000 Rear Axle Model: NA Independent Front Suspension: Yes Full Coach Raise and Lowering Susp.: No Tag Axle Unloading System: Yes Front Susp. Kneeling System: Yes	
Transmission Options Trans Make: ALLISON Trans Model: 3000/4000 Trans Speed: 6	



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes

Steer Axle Brakes:	50%	50%	(1)
Drive Axle Brakes:			(2)
	70%	70%	(3)
			(4)
			(5)
			(6)

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	FIRESTONE FS400

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		10 / 32nd HIGHWAY / V	9 / 32nd HIGHWAY / V
RIGHT	15 / 32nd HIGHWAY / V 	 	 
FRONT		11 / 32nd HIGHWAY / V	/ 32nd /
LEFT	 13 / 32nd HIGHWAY / V	 	 
		11 / 32nd HIGHWAY / V	14 / 32nd HIGHWAY / V

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732

CONDITION REPORT

	Engine Compartment Area	COMMENTS
X	Power/Manual Steering Fluid Level	P/S FLUID OVER FULL
	Operational Test	COMMENTS
	In Cab Inspection	COMMENTS
	Outside Inspection	COMMENTS
	Under Vehicle Inspection	COMMENTS
	Tires/Wheels/Brakes	COMMENTS
X	Tires/Wheels	1 TIRE LESS THAN 10/32 TREAD

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Power/Manual Steering Fluid Level	X P/S FLUID OVER FULL
Tires/Wheels	X 1 TIRE LESS THAN 10/32 TREAD
ECU READINGS	ACTIVE/INACTIVE FAULTS-REPORT ATTACHED
ENTRY DOOR	BOOT TORN
TPMS SYSTEM	LIGHT ON-TIRE OVER INFLATED

COMMENTS:

UNABLE TO CHECK/INSPECT REAR AXLES BRAKES AND REAR AXLE MODEL OR RATIO-UNIT IS TO LOW TO GO UNDER BENDIX TIRE PRESSURE MONITOR SYSTEM



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)


HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER




RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER




LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO
BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732



FLOOR OF BUS, FRONT TO
BACK



INSIDE OF BUS, BACK TO
FRONT



FLOOR OF BUS, BACK TO
FRONT



INSIDE RESTROOM #1



INSIDE RESTROOM #2



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12




ADDITIONAL 13




ADDITIONAL 14



ADDITIONAL 15



ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 18



ADDITIONAL 19



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

03/09/2021

FLEET NAME

UNIT NUMBER

5621

VIN (LAST 8)

HC713784

PO NUMBER

INSPECTOR: 5436

INSPECTION ID

137732

Item	Status	Details
Engine Oil Pressure	OK	15.0 PSI
Engine Coolant Temp	OK	180 F
Engine Air Temp	OK	120 F
Engine RPM	OK	1200
Engine Hours	OK	1200
Engine Miles	OK	1200
Engine Oil Level	OK	15.0 PSI
Engine Coolant Level	OK	180 F
Engine Air Filter	OK	120 F
Engine RPM	OK	1200
Engine Hours	OK	1200
Engine Miles	OK	1200
Engine Oil Level	OK	15.0 PSI
Engine Coolant Level	OK	180 F
Engine Air Filter	OK	120 F

ADDITIONAL 20



ADDITIONAL 21



Power/Manual Steering Fluid
Level