

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

| | | | | | |
|--------|-----------|--------|----------------|------------------|------------|
| Make: | Bobcat | Type: | Mini Excavator | Inspector: | GP |
| Model: | E32 T4 | Hours: | 2710 | Inspection Date: | 11/14/2024 |
| SN: | B3Y115753 | Year: | 2021 | | |

SPECIFICATIONS

| | | | | | | |
|---------------------------------|---|-----------------|---------------|------------------------------------|-----------|---------------------------|
| ROPS: | Yes | Hours: | 2710 | | | |
| Enclosed Cab: | No | Cab Heat: | No | Cab A/C: | No | Controls: Standard |
| Attachment on Machine: | 36" Bucket | | | | | |
| Additional Attachments: | THUMB ATTACHMENT | | | | | |
| 2-Speed: | No | Engine MFR: | DOOSAN | Tracks | | |
| High Flow Hydraulics - Sticker: | No | Power Bob-Tach: | No | Keyless Start: Yes | | |
| Backup Camera: | No | Ride Control: | No | Deluxe Instrumentation: Yes | | |
| Hydraulic X-Change: | Yes | | | | | |
| Comments and Defects: | UNIT LOCATED AT BOBCAT OF BROWARD, | | | | | |

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

| Tire Fault Legend | | | |
|------------------------------|---------|----------|--------------------------------|
| C - Cut WD - Wheel Damage | D - Dry | F - Flat | M - Mismatched Tread / Casings |

| TRACKS | |
|--|--|
| Make: NA Part #: NA Measure: 32 / 32 Condition: GOOD Tread Remaining: Over 50% Fault: | Make: NA Part #: NA Measure: 32 / 32 Condition: GOOD Tread Remaining: Over 50% Fault: |

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

CONDITION REPORT

| | Check | Comments / Deficiencies |
|-----|---------------------------------|--|
| X | Visual Inspection | CONCRETE |
| X | Operational Test | FAILED - MOST MOVEMENTS - HYDRAULIC ACTUATOR SWITCH ON LEFT SIDE MISSING |
| N/A | Lift Cylinders | |
| N/A | Tilt Cylinders | |
| N/A | Boom Arms Operations | |
| ✓ | Seat | GOOD CONDITION |
| N/A | Tailgate Lights | |
| ✓ | Working Lights | GOOD CONDITION |
| N/A | Front Door | |
| N/A | Rear and Top Window | |
| N/A | Side Glass Complete | |
| ✓ | Boom Arms Damages | NO DAMAGES |
| ✓ | Rear Door | OPENS AND CLOSES AND STAYS CLOSED |
| ✓ | Mufflers | GOOD CONDITION |
| ✓ | ROPS Condition | GOOD CONDITION |
| N/A | Power Bob-Tach Condition | |
| N/A | Cab A-C Condition | |
| N/A | Cab Heat Condition | |
| ✓ | Intake Screen | GOOD CONDITION |
| ✓ | Eng. Compartment | |
| N/A | Hydraulic X-Change Condition | |
| ✓ | Customer Decals Visible on Unit | NO |
| X | Error Codes | HYDRAULIC WARNING DISPLAYED - DIAGNOSE |
| X | Condition Report | RIGHT SIDE DOOR LATCH BENT / TWISTED - DOOR WILL NOT LATCH SHUT |
| X | Condition Report | LEFT / RIGHT SIDE LOWER BODY PANELS DENTED |
| X | Condition Report | LEFT TRACK MOUNTED BACKWARDS |
| X | Condition Report | UNIT DECALS NOT LEGIBLE / MISSING |
| X | Condition Report | HYDRAULIC ON STICK WORN / FRAYED |

PHOTOS



Front Left



Front Right



Rear



Seating / Interior

PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

