



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13355280 - 2022 Rubble Master RM100 GO Closed Circuit Impact Crusher



Item Details:

- Features: Tier 4, Rubble Master 100GO! 40 in Impact Crusher, 8 ft x 0 ft 52 in Single Deck Screen, Spray/Wash System, 47 in Wide Feed Conveyor, 40 in x 24 ft Crusher to Screen Conveyor, 40 in Wide Under Screen Conveyor, 17 in Wide Right Discharge Conveyor, 40 in Wide End Discharge Conveyor, 32 in x 6 ft Cross Belt Magnet, Radio and Cable Remote Control, 16 in Triple Grouser Track Shoes
- Meter Reading: 1,975 Hours
- Serial # : RM100GO1-05.662
- Inspection Completed: 5/5/25

Shipping Details:

- Location Tennessee (Nashville area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.


Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	RM100GO1-05.662	
Hour Meter / Odometer	1975 hrs	
v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		
v3 General Appearance # 4		

Control Station		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Gauges	Operational	
Engine Controls	★★★★☆	
Crusher/Screen Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		

Electrical


The generator was not load checked during the inspection. IronPlanet does not guarantee the generators ability to run at its full rated kW output.

Item	Assessment	Photo
Disconnect Switch	Not operationally checked	
Cables and Connections	★★★★☆	
Electrical # 1		
Electrical # 2		
Electrical # 3		
Electrical # 4		



Electrical # 5		
Electrical # 6		
Electrical # 7		
Electrical # 8		
Electrical # 9		

Engine		
Item	Assessment	Photo
Emission Certification Label	None found	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		

DEF / AdBlue Tank		
Limited Function Check (Engine)	The engine started and ran.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Crusher Door Cylinders	★★★★☆	
Conveyor Cylinders	★★★★☆	

Power Travel Drive System	★★★★☆ Travels properly	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		



Chassis		
Item	Assessment	Photo
Feed Hopper	★★☆☆☆ Length @ top: 140, Width @ top: 80	
Jaw, Blow Bar and Anvil Wear Surface	★★☆☆☆ Unable to gain access	
Crusher Drive System	★★☆☆☆	
Discharge Conveyor Condition	★★☆☆☆	
Screen Cloth	★★☆☆☆	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		

Chassis #9		
------------	--	---

Undercarriage		
Item	Assessment	Photo
Left Roller Frame		
Left Track Tensioner		
Left Track Pads		
Left Grouser Height	18 mm	
Left Track Links		
Left Track Bushings	Bushings have not been turned	

Left Carrier Rollers		
Left Track Rollers		
Left Idler		
Left Sprocket		
Right Roller Frame		
Right Track Tensioner		
Right Track Pads		

Right Grouser Height	18 mm	
Right Track Links		
Right Track Bushings	Bushings have not been turned	
Right Carrier Rollers		
Right Track Rollers		
Right Idler		
Right Sprocket		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved