



Aspen Field Services

Job #: 34439 /

Serial #: APP547318

For more information, visit:

wellsfargo.com/equipmentseller

ATLAS COPCO COMPRESSOR V21



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/S8QNy46rzA7nuWjLs/full_report_0034439_S8QNy46rzA7nuWjLs.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details

Year	2018
Make	Atlas
Model	V21 Stage IV
Type	Air Compressor
VIN	APP547318
Inspection Date	09/30/2021
Location of Business	JJ Kane Auctioneers - 1402 Conshohocken Rd, Plymouth Meeting, PA, 19462
Hours	775
Warning Lights	None
Operational Test	Passed
Body Paint	Good Condition
Engine Doors	Good Condition
Engine Compartments	Good Condition
Back Right Tire Condition	Fair
Back Right Tire Brand	Sailun



Aspen Field Services

Job #: 34439 /

Serial #: APP547318

For more information, visit:

wellsfargo.com/equipmentseller

ATLAS COPCO COMPRESSOR V21

Inspection Details Cont'd

Back Right Tire Size	215/75R17.5
Back Right Tire Tread Depth Measurement	15/32"
Back Right Tire Tread Depth Percentage	47%
Front Right Tire Condition	Fair
Front Right Tire Brand	Sailun
Front Right Tire Size	215/75R17.5
Front Right Tire Tread Depth Measurement	16/32"
Front Right Tire Tread Depth Percentage	50%
Back Left Tire Condition	Fair
Back Left Tire Brand	Sailun
Back Left Tire Size	215/75R17.5
Back Left Tire Tread Depth Measurement	15/32"
Back Left Tire Tread Depth Percentage	46%
Front Left Tire Condition	Fair
Front Left Tire Brand	Sailun
Front Left Tire Size	215/75R17.5
Front Left Tire Tread Depth Measurement	15/32"
Front Left Tire Tread Depth Percentage	47%
Comments	Wheel bearing cap missing.

Inspection Details Cont'd