



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
 504 - Wells Fargo MSG  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 09/08/2020 | | GR030341 |

**INSPECTOR:** 5750  
**INSPECTION ID**  
 125087

<b>Year, Make:</b>	2016, JOHN DEERE	<b>Full VIN:</b>	1TC770AVCGR030341
<b>Model:</b>	7700A	<b>Engine Make:</b>	JOHN DEERE
<b>Engine Model:</b>		<b>Clean air idle:</b>	
<b>Classification:</b>	Utility vehicle		

**Note and photograph any body damage including scrapes, dents and glass:**  
 NONE

**Note and photograph any major oil or fluid leaks:**  
 NONE

**Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.**  
 NONE

**Note any unusual engine noises or knocks:**  
 GOOD

**List and photograph any tires with uneven wear:**  
 GOOD

**Additional Comments:**

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
HOURS	2129



DEKRA Services Inc.  
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT  
504 - Wells Fargo MSG  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
09/08/2020 | | GR030341 |

INSPECTOR: 5750  
INSPECTION ID  
125087



VIN



ADDITIONAL 13




ADDITIONAL 12



ADDITIONAL 10



FRONT RIGHT



ADDITIONAL 5



SEAT



CONTROLS



ENGINE



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 7



Tire



ADDITIONAL 8



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT			
504 - Wells Fargo MSG			
INSP DATE	FLEET NAME	VIN (LAST 8)	PO NUMBER
09/08/2020		GR030341	

**INSPECTOR:** 5750  
**INSPECTION ID**  
125087



ADDITIONAL 9



ADDITIONAL 14



ADDITIONAL 11