

1000 K-TEC 1237

UNIT: KS03077

[Download Reconditioning Printout](#)



UNIT SPECS

LOCATION

Wells Fargo (IMS)

Please call Pickup Support for location information
Davenport, FL 33897

GENERAL APPEARANCE

| | | | |
|--------------------------|---------|------------------------------|--------|
| UID | KS03077 | Make and Model Review | 4 Tire |
| General Condition | Good | | |

CHASSIS

| | | | |
|--|------|--------------------------------------|--------------------------|
| Hitch Condition (Structural) Rating | Good | Bowl Condition Rating | Good |
| Floor Rollers/Guides Rating | Good | Ejector Face Condition Rating | Good |
| Apron Condition Rating | Good | Push Block Rating | Good |
| Cutting Edges Rating | Good | Tire Size(s) | Tire Size: 26.5R25 Tires |

RECONDITIONING

| | |
|--|--------------|
| Paint Damaged on Rear Push Bumper | \$350 |
| Total | \$350 |