







7775

PREVOST

CA 691

X2











5/80R22.5 (L)	22.5X9	KPA (PSI)	827 (120)	
5/80R22.5 (L)	22.5X9	586 (85)		D
5/80R22.5 (L)	22.5X9	689 (100)		S

ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE
ON THE DATE OF MANUFACTURE SHOWN ABOVE.

2PCG33499GC736079

#408301

PE : BUS B/A

PREVOST®

RED BY: PREVOST
AR : STE - CLAIRE, QUE.



OF MFG.
DE FAB.

03/16

000 LBS).

TIRES/
PNEUS

RIMS/
JANTES





X30





CAUTION
110 VOLTS







MC #33625
USDOT #73





737745







Automotive North America, INC.

DEKRA


Commercial Vehicle Inspection Service

770-971-37









Automotive America, INC.

Commercial Vehicle Inspection Services

770-971-3788

ANTIGEL LONGUE DURÉE
EXTENDED LIFE COOLANT
ANTICGELANTE DE
LARGA DURACIÓN



ATTENTION
CONSULTER
LE MANUEL

NE PAS UTILISER D'EAU
OU D'ANTIGEL NON
RECOMMANDÉ

NE PAS UTILISER D'ANTIGEL NON RECOMMANDÉ

90280 826100116 100%
EXTRAIR 100% D'EAU
TOUTES LES 100000 KM



ATTENTION: HOT SURFACE
TENDER LIFE EGG LANT
ATTENTION: HOT SURFACE
TENDER LIFE EGG LANT



WARNING: HOT SURFACE
TENDER LIFE EGG LANT
ATTENTION: HOT SURFACE
TENDER LIFE EGG LANT



DO NOT POWER WASH
ALTERNATORS





























2016 Prevost Vehicle
 Volvo D13
 Allison 3000i48
 Bendix EC-60

Vehicle Information
 VIN: 2PCG33499GC736079
 Manufacturer: Prevost
 Model: X3 Coach
 Model Year: 2016

Overview Regen Status Data


DPF Derate
 No Derate

Regen Zone
 0/1

Regen Needed
 No

Inhibit State
 Inhibited

Click an aftertreatment component for additional information.



...	Count
N/A	N/A
1	1
2	1
3	4
4	6

DPF Derate
 Low

7 hrs

3 gal

Active Regen Time



Acquiring veh

2016 Prevost Vehic

Volvo D13

Allison 3000M4

Bendix EC-60

Vehicle Information
VIN: 2PCG33489GC78079
Manufacturer: Prevost
Model: X3 Coach
Model Year: 2016

Data Monitor

All
Power Diagram
Data Groups
Temperature
Switches
Status Indicators
Pressure
Percent
Electrical

Companion
All

hp

Search

Data Monitor

No Data Available

Clear Selection

Graph

Add to Data Group

Connector Info

Bus Statistics

FMI Assistance

Fault Status Assistance

Industry Terms


Electrical Tips

Regen Zone Info

EPA Assistance

Close

F	Count
N/A	N/A
1	1
2	1
3	4
4	1



DPF Delete

Low

Low Fuelable

8.7 hrs

6.2 gal



2016 Prevost Vehicle
 Volvo D13
 Allison 3000/4
 Bendix EC-60

Vehicle Information
 VIN: 2PCG33499GC736079
 Manufacturer: Prevost
 Model: X3 Coach
 Model Year: 2016

Data Monitor

Power Diagrams | Data Groups | Temperature | Switches | Status Indicators | Pressure | Percent | Electrical

Data Group: **079**

Selected	Description	Parameter Value	Units	Component	Network Speed
☒	High Resolution Total Vehicle Dis	111.811.871	hrs	D13	11929 (High)
☒	Total Engine Hours	4.118.70	hrs	D13	11929 (High)

...	Count
h/w	N/A
0	1
1	1
2	4
3	4

DPP Denote

Low

Low Fuel Warning

67 hrs

6.2 gal

Print Date: June 09, 2021 12:28 pm

VIN	2PCG33499GG756070
Vehicle Make	Prostar
Model	X3 Coach
Model Year	2010

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Volvo D13	15433310	23389571.23434077 23820375	J1939 (High) 15765 (CAN)
Transmission	Airbus 3000/4000 5th Gen	BR6283A200190324	W15BICD_PC_5J09F C15200105402D	J1939 (High) 15765 (CAN)
Brakes	Bendix EC-80 Advanced ABS	Q181511481	BB41062 BB41065	J1939 (High)

Vehicle Key Data Points

Parameter Description	Value	Parameter Description	Value
Avg Fuel Econ	5.80 mpg	Idle Fuel Used	3,350.30 gal
DPF Soot Level	Low	Total Idle Hrs	2,078.80 hrs
DPF Delete	Low	Idle Shutdown	Not Available
Total Engine Hrs	4,318.80 hrs	Battery Potential	28.40 volts
Cruise Spd Limit	Not Available	Road Speed Limit	75.00 mph
Malfunctor Indicator Lamp	Off	Red Stop Lamps	Off
Anteil Warning Lamp	Off	Protect Lamp	Off
Parking Brake Switch	On	(DPF) Lamp Command	Off
Exhaust System High Temp	Off	ABS Control Status	Not Available
ABS Control Status, Trailer	Not Available	Engine Speed	1000 rpm
Odometer	111,811.83 mi	Engine Odometer	111,811.83 mi
Instrument Cluster Odometer	111,811.83 mi	Fuel	13%
Engine Oil	Normal	Coolant	Normal
Diesel Exhaust Fluid	66%		

Vehicle Issues

 **Exhaust Fluid** Low

Faults

Print Date: June 09, 2021 12:28 pm

Status	Component	Description	Lookup Code	FMI	Count
Inactive	O11	Valve Compression Brake (VCB) Control Oil Temperature Too Low. No additional information	P114000	N/A	N/A
inactive	O12	Reductant Level Moderately Low. No additional information	P114300	N/A	N/A
inactive	O13	Lost Communication With ECM According To Turbocharger/Supercharger Control Module "A". No additional information	P114800	N/A	N/A
Inactive	EC-88 Advanced ABS	Brake Demand/Load Sensors - PS1 Open/Shorted or PS Supply Voltage Error (Flash Code 24-1 or 24-5)	SPN 1067	2	1
Inactive	EC-88 Advanced ABS	Brake Demand/Load Sensors - PS2 Open or Shorted (Flash Code 24-2)	SPN 1068	2	1
Inactive	EC-88 Advanced ABS	J1939 Serial Communication - J1939 Retarder (Flash Code 11-2)	SPN 632	14	4
Inactive	EC-88 Advanced ABS	J1939 Serial Communication (Flash Code 11-10 or 11-11 or 11-12 or 11-13 or 11-3 or 11-4 or 11-5 or 11-6 or 11-7 or 11-8 or 11-9)	SPN 632	2	4
Inactive	Exhaust Emission Controller	System Voltage Low	P056200	N/A	1
Inactive	Retardment Cluster	SAB - Service Brake Circuit 1 Air Pressure - Data valid but below normal operational range - Most severe level	SPN 1087	1	22
Inactive	Retardment Cluster	SAB - Service Brake Circuit 2 Air Pressure - Data valid but below normal operational range - Most severe level	SPN 1088	1	18



PREVOST®

MANUFACTURED BY: PREVOST
FABRIQUE PAR : STE - CLAIRE, QUE.

DATE OF MFG.
DATE DE FAB.

EC

G. V. W. R. : 24040 KG. (53000 LBS).
P. N. B. V. :

AXLES/
ESSIEUX

G. A. W. R. /
P. N. B. E.

TIRES/
PNEUS

RIMS/
JANTES

COLD
INFLATION
PRESS. /
PRESS. A
FROID

SINGLE
OR DUAL/
SIMPLE
OU
DOUBLE

KPA (PSI)

	KG	(LBS)				
FRONT : AVANT :	7484	(16500)	315/80R22.5 (L)	22.5X9	827 (120)	S
INT : DIFF. :	10206	(22500)	315/80R22.5 (L)	22.5X9	586 (85)	D
REAR : TANDEM :	6350	(14000)	315/80R22.5 (L)	22.5X9	689 (100)	S

THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE
SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VEHICLE IDENTIFICATION NO.
NO. IDENTIFICATION VEHICULE

2PCG334996C736079

#408301

TYPE : BUS B/A













7775

PREVOST

8364BA

X3



Door
Open

9.0 2
689.0

11:25

111811.8mi

LOW SULFUR DIESEL FUEL ONLY

















VOLVO

VOLVO POWERTRAIN CORPORATION

ENGINE FAMILY P41TH2 NGT

FAMILLES DE MOTEURS:

DISPLACEMENT ADVERTISED HP @ RPM

CYLINDRES

PUISS. SPEC @ TOURS/MIN

Cyl

105/700

ENGINE MODEL D13M35P

MODELE MOTEUR:

FUEL RATE @ ADVERTISED HP

DEBIT DE CARB. @ PUISS. SPEC

mm³ / STROKE

256

mm / COUP

SERIAL NO. 1134043

NO. SERIE:

IDLE SPEED

RALENTI

550-700RPM

ENGINE BRAKE

FREIN MOTEUR

I-VEB

THIS ENGINE CONFORMS TO U.S. EPA AND CALIFORNIA REGULATIONS APPLICABLE TO 2015 MODEL YEAR HEAVY
HEAVY DUTY ENGINES AND HAS A PROBABLY INTENDED SERVICE APPLICATION AS A HEAVY HEAVY-DUTY DIESEL ENGINE.

Ce moteur est conforme aux réglementations de Californie et de l'Agence de Protection de l'Environnement
des Etats-Unis applicables aux moteurs diesel Heavy Duty (Gomme lourde) modélisé 2015.
La destination application Caléenne aux usages de type gomme lourde (Heavy-Heavy-duty).

EXHAUST EMISSIONS CONTROL SYSTEM
Système de réduction des émissions

THIS ENGINE IS CERTIFIED TO OPERATE ON
ULTRA LOW SULFUR DIESEL FUEL ONLY

100% EGR, DCR, EGR, DCR, PSCR, SCR, AMOX

VALVE LASH (JER SOUPPIER)

INLET ROCKER 0.2mm

ADMISSION CULBUTEUR

EXHAUST ROCKER 1.0mm

ECHAPPEMENT CULBUTEUR

DELEGATED ASSEMBLY

LABEL NO

22520196





REFRIGERANT
R-134a
CHARGE NOMINAL 13.82 KG
NOM
FILLING POINT

CAUTION