



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

05/19/2020

FLEET NAME

VIN (LAST 8)

PO NUMBER

FM050417

INSPECTOR: 5750

INSPECTION ID

117875

Year, Make:	2015, JOHN DEERE	Full VIN:	1M0220SAHFM050417
Model:	220SA	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

Note and photograph any body damage including scrapes, dents and glass:

GOOD

Note and photograph any major oil or fluid leaks:

GOOD

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.

GOOD

Note any unusual engine noises or knocks:

GOOD

List and photograph any tires with uneven wear:

WORN

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
ALL TIRES WORN	UNDER 50%



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

05/19/2020

FLEET NAME

VIN (LAST 8)

FM050417

PO NUMBER


INSPECTOR: 5750

INSPECTION ID

117875



FRONT LEFT



SERIAL #



FRONT



LEFT REAR



RIGHT REAR



TIRES



TIRE



ADDITIONAL 1



ADDITIONAL 2