

CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Make:	Komatsu	Type:	DOZER	Inspector:	GP
Model:	D61PXi24	Hours:	8290	Inspection Date:	8/30/2024
SN:	KMT0D129KKBB61141	Year:	2019		

SPECIFICATIONS

Tracks	Tracks Model:	SINGLE GROUSER	Cut:	No	Controls:	FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER
	Tread Depth:	50/32	Tread %:	Over 50%		
Enclosed Cab:	Yes	Heat:	Yes	A/C:	Yes	
Bucket Width:	152	Teeth:	Without	Damaged:	No	
Other Options:	12'6" BLADE - TILTS AND SWINGS SIDE TO SIDE REAR CAMERA					

CONDITION REPORT

	Check	Comments / Deficiencies
✓	Frame	
✓	Boom & Uprights	
✓	Lift Cylinders	
✓	Tilt Cylinders	
✓	R H Drive	
✓	L H Drive	
✓	Variable Speed	
✓	Engine	QUIET
✓	Appearance	GOOD
N/A	Describe Missing Parts	
✓	Attachment Inspection	
X	Condition Report	DOME LIGHT COVER MISSING
X	Condition Report	NOTE: BATTERIES DEAD - JUMPED OFF - UNIT RESTARTED AFTER RUNNING

PHOTOS



Seating / Interior



Rear



Front Right



Front Left

PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

