



# **Detailed Equipment Information**

Print

Download All Photos

#### 2024 VERMEER SC362 / ENV


- General Appearance
  Control Station
  Engine
  Drivetrain
  Hydraulics

- ChassisUndercarriageLogistics Information

# **GENERAL APPEARANCE**

То Тор


SERIAL NUMBER / VIN  SERIAL NUMBER LOCATION  Rear Frame Passenger Side  SELLER REFERENCE NUMBER  Seller Reference or Fleet Number:  TIRES/ UNDERCARRIAGE  Percentage Rating:, 90  HOUR METER / ODOMETER  51 hrs  CONDITION  Overall Condition for Age:, Very Good  FEATURES  2023 US EPA Label, Briggs & Stratton 26.1 kW Engine, 20 in Grinding Wheel			
SELLER REFERENCE NUMBER  Seller Reference or Fleet Number:  TIRES/ UNDERCARRIAGE  Percentage Rating:, 90  HOUR METER / ODOMETER  51 hrs  CONDITION  Overall Condition for Age:, Very Good  FEATURES  2023 US EPA Label, Briggs & Stratton 26.1 kW	SERIAL NUMBER / VIN	1VRF112YCR1005738	
TIRES/ UNDERCARRIAGE  Percentage Rating:, 90  HOUR METER / ODOMETER  51 hrs  CONDITION  Overall Condition for Age:, Very Good  FEATURES  2023 US EPA Label, Briggs & Stratton 26.1 kW	SERIAL NUMBER LOCATION	Rear Frame Passenger Side	
HOUR METER / ODOMETER  51 hrs  CONDITION  Overall Condition for Age:, Very Good  FEATURES  2023 US EPA Label, Briggs & Stratton 26.1 kW	SELLER REFERENCE NUMBER	Seller Reference or Fleet Number:	
CONDITION Overall Condition for Age:, Very Good  FEATURES 2023 US EPA Label, Briggs & Stratton 26.1 kW	TIRES/ UNDERCARRIAGE	Percentage Rating:, 90	
FEATURES 2023 US EPA Label, Briggs & Stratton 26.1 kW	HOUR METER / ODOMETER	51 hrs	Amaza.
	CONDITION	Overall Condition for Age:, Very Good	
	FEATURES		











#### **ENGINE**

Back To Top **EMISSIONS STATUS** Other 2023 US EPA Label **ENGINE** Briggs & Stratton 26.1 kW Engine LIMITED FUNCTION CHECK The engine would crank but would not run.

- Photo 1Photo 2Photo 3Photo 4

# **DRIVETRAIN**

Back To Top LIMITED FUNCTION CHECK The drivetrain could not be operationally checked.

• Photo 1
• Photo 2

# **HYDRAULICS**

Back To Top LIMITED FUNCTION CHECK The hydraulic system could not be operationally checked.

Photo 1Photo 2

#### **CHASSIS**

Back To Top FEATURES 20 in Grinding Wheel

- Photo 1Photo 2Photo 3

#### **UNDERCARRIAGE**

Back To Top

- Photo 1Photo 2Photo 3Photo 4

# **LOGISTICS INFORMATION**

SHIPPING DIMENSIONS 9 ft Long x 4 ft Wide x 5 ft Tall Back To Top

DISCLAIMER

General

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

#### Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole

#### Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes

© 2012 Ritchie Bros. Auctioneers Privacy Statement | Legal Disclaimer