



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
 504 - Wells Fargo MSG  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 05/19/2020 | | FM050423 |

INSPECTOR: 5750  
 INSPECTION ID  
 117878

Year, Make:	2015, JOHN DEERE	Full VIN:	1M0220SATFM050423
Model:	220SA	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

**Note and photograph any body damage including scrapes, dents and glass:**  
 SIDE COVERS WORN

**Note and photograph any major oil or fluid leaks:**  
 good

**Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.**  
 good

**Note any unusual engine noises or knocks:**  
 good

**List and photograph any tires with uneven wear:**  
 worn under 50%

**Additional Comments:**

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
SIDE COVERS	WORN
TIRES	BELOW 50%



DEKRA Services Inc.  
Customer Service 770-257-0107

### TRACTOR QUICK CHECK INSPECTION

CLIENT  
504 - Wells Fargo MSG  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
05/19/2020 | | FM050423 |

INSPECTOR: 5750  
INSPECTION ID  
117878



FRONT RIGHT



ENGINE TAG



FRONT LEFT



FRONT



MODEL #



ENGINE



LEFT REAR



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7