



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

05/19/2020

FLEET NAME

VIN (LAST 8)

PO NUMBER

FR030016

INSPECTOR: 5750

INSPECTION ID

117866

Year, Make:	2015, JOHN DEERE	Full VIN:	1TC770AVVFR030016
Model:	7700A	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

Note and photograph any body damage including scrapes, dents and glass:

GOOD

Note and photograph any major oil or fluid leaks:

GOOD

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.

GOOD

Note any unusual engine noises or knocks:

GOOD

List and photograph any tires with uneven wear:

ABOVE 50%

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
HOURLY METER 1534	



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

05/19/2020

FLEET NAME

FR030016

VIN (LAST 8)

FR030016

PO NUMBER

INSPECTOR: 5750

INSPECTION ID

117866



45 DEGREE BEAUTY SHOT



VIN



RIGHT FRONT



LEFT FRONT



LEFT SIDE



FRONT



HOURLMETER



ODOMETER



ENGINE



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 13



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 7



ADDITIONAL 10



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

05/19/2020

FLEET NAME

FR030016

VIN (LAST 8)

FR030016

PO NUMBER

INSPECTOR: 5750

INSPECTION ID

117866



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 14



ADDITIONAL 15