



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | FM060471 |

INSPECTOR: 5750
 INSPECTION ID
 117882

Year, Make:	2015, JOHN DEERE	Full VIN:	1M0220EAAF060471
Model:	220E	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		
Note and photograph any body damage including scrapes, dents and glass:			
WARE ON SIDE COVERS			
Note and photograph any major oil or fluid leaks:			
NONE			
Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.			
NONE			
Note any unusual engine noises or knocks:			
NONE			
List and photograph any tires with uneven wear:			
TIRES UNDER 50%			
Additional Comments:			

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
2 SIDE COVERS	WORN
2 TIRES	WORN UNDER 50%



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | FM060471 |

INSPECTOR: 5750
 INSPECTION ID
 117882



LEFT REAR



VIN



FRONT RIGHT



FRONT



RIGHT REAR



LEFT FRONT



ENGINE



MODEL



CONTROLS



REAR



1



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 8