

ABC Incoming Inventory Check-In Form

*Year 2016 *Make VanHool *Model Tx45

*Full VIN YE2YCB2B4G2041453 *Date Received 2/28/2020

*Owner WDG
(Leasing Repo, Bank Repo, Customer, etc.)

*Location of Coach ABC Newark
(Physical Location)

Suggested Retail* _____

Odometer Reading* 99435

Special Programs _____

Interior Condition New Good Fair Poor

Status _____

Footrests _____ N Y

Parking Stall _____

Lavatory* Flush Non-Flush None Center or Rear

Acquired From* _____

Holding Tank _____ N Y

Engine* Make: Cummins Model: ISX12

of Monitors 1 CRT Flat Screen

Engine Miles 99435

Parcel Racks Enclosed None Open Contoured

Jake (Engine Brake) _____ N Y

Seat Manufacturer* VanHool
Modified CPR Other

Retarder (Transmission Brake) _____ N Y

Seat Model _____

Emission Type 2

Seat Cover Color Blue/Black

Transmission* Make: Allison Model: B500

Seating Configuration Forward-Facing Perimeter

Transmission Miles 99435

Seatbelts* 2 point 3point None

Transmission Type Auto Manual

of Passengers* 52

Exterior Condition New Excellent Fair Good Poor

Wheelchair Location* Front In-Step None Ramp Rear

Paint Color* White

Lift Model* N/A

Glass Condition New Excellent Fair Good Poor Broken

Lift Serial Number* N/A

Rear Window _____ N Y

Engine Monitor Display _____ N Y

Glass Top _____ N Y

Fire Suppression _____ N Y

Tire Make Firestone Good year Michelin Multiple Continental Toyo Double Coin

Shades _____ N Y

Tire Condition New Marginal OK

Cordless Mic _____ N Y

Wheels Aluminum Polished Aluminum Steel S/S Inserts

Tire Monitor _____ N Y

Spare Tire _____ N Y

Backup Camera _____ N Y

Exterior Comments _____

Tag Unloader _____ N Y

Door Key Code 124

Kneeler _____ N Y

Entry Doors 1 2 3

DVD _____ N Y

Chassis Manufacturer VanHool

PreHeat Timer _____ N Y

Commercial Plate 58704CA

110 V Outlets _____ N Y

Additional Comments: _____

Required Signatures: ABC Matthew Barwick

Operator [Signature]

RVP/GM Approval _____

Date 2/28/20

Check If Complete Pictures: Online ___ & Google Drive ___ Checklist: If new to location, One Drive ___ JED: Updated / Bought In ___





0027



BODY INSPECTION FORM

VIN # YE2YC82B4G2041453

Van Hool TX45



PROCEDURE: Place the defect number in the appropriate area on the drawing above, circle the affected area and placing an "X". Also note all dents, any glass issues, or any body related items that are not listed below:

- COMMENTS: 1. Scratches around Pass. tail light
2. scratches on BIK rack
3. scratches on Pass mirror

- 1. CRACKS
- 2. CHIPS
- 3. DENTS
- 4. GLASS: FOGGED

INSPECTED BY: Matthew Boubert

DATE: 2/28/2020