

# INSPECTION SUMMARY

## 2017 Claas Jaguar 980 Forage Harvester

SN 49800108

Buckeye, Arizona

July 31, 2020

**Equipment Inspection Location:** 22904 West Southern Avenue, Buckeye, Arizona 85326

**Inspection Date:** July 27, 2020

**Description:** 2017 Claas Jaguar 980 Forage Harvester

**Serial Number:** 49800108

**Hours:** 3733 Metered Engine Hours, 2699 Metered Cutter Hours

**General Description:** Cab, 884-HP Diesel Engine, Hydrostatic Transmission, 36-Knife Drum, Rear Discharge Chute, 710/70R38 Front Tires (Average), 600/65R28 Rear Tires (Average)

**Cab:** Good condition. The interior of the cab is in overall good condition. No rips in seat, buddy seat or headliner. A few minor stains. No apparent odor and not excessively dirty.

**Cab Glass:** The back window is broken. There is a new window in the shop ready to be installed. The remainder of the glass is in good condition. No chips, cracks or window fogging.

**Cab Systems:** Good condition. No dash warning lights displayed. All lights, heat and A/C functioning and maintained.

**Cab Components:** Good condition. All components functioning and maintained.

**Engine:** 884-HP Diesel Engine. Good condition. Readily starts and shuts down crisply.

**Transmission:** Hydrostatic Transmission. Good condition. Seemed to shift properly.

**Tires:** 710/70R38 Front Tires, 600/65R28 Rear Tires. Average condition. No side wall damage or weather cracking. Approx. 75% tread life remaining.

**Mechanical Condition:** Good condition. This unit runs, drives and operates as it was manufactured to do.

**Exterior Condition:** Overall good condition. No paint chips, peeling paint or fading. No scratches in the paint or plastic. A few decals starting to peel on the rear of the equipment.

**Overall Condition:** Good condition. This unit runs, drives and operates as it was manufactured to do.

**Maintenance:** No maintenance records were provided.

**Estimate of Repairs:** N/A

**Inspector Notes:** Good condition. This unit runs, drives and operates as it was manufactured to do.

# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures



# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures





# EQUIPMENT INSPECTION

2017 Claas Jaguar 980 Forage Harvester  
SN 49800108  
Buckeye, Arizona

July 31, 2020

## Representative Pictures

